

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & 35 of T31-6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7947)

-----  
Set ¼ sec. post on SW. slope, from which  
A Fir 20" dia., bears S.4°30'W., 15 lks. dist.  
A Fir 6" dia., bears N.31°E., 73 lks. dist.

Survey by Orrin K. Frederick - For: Boise Cascade Timberlands of Oregon - Feb. 21, 1985 - M 90-67 and C.S. File 63/11

-----  
After a diligent search, I did not find any definite evidence of the corner position or bearing trees, except a Roseburg Lumber Co. location poster, circa 1961, which reads "people seem to think this ¼ S - can't find any scribe marks." posted on a stump. I cut into said stump which had the lower portion of a face with no definite scribing or axe work but fit proper diameter and direction for SW BT.

I then Set a 5/8" x 30" rebar for the corner with properly marked Alum. cap at proportionate distance between adjacent section corners.

New BTs -6" Fir bears, S.49°45'W., 24.03 ft. mkd. ¼ S2 LS1987 BT.

7" Fir bears, N.40°W., 19.14 ft. mkd. ¼ S35 LS1987 BT.

Aforementioned stump fit position within 5 ft. Cor. lies on gentle southerly slope approx. 120 ft. southerly of Rd. #31-6-35.

Fd. Ok by Lloyd D. Smith, L.S. #1101 - For: State of Oregon, Dept. of Forestry - June 1995 - M 122-15