

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8666)

-----  
Set a Fir post, 3 ft. long, 3" sq., 22" in the ground for the 1/4 sec. cor., mkd. 1/4 S on N. face, from which  
A Fir 8" dia., bears N.5°E., 15 lks. dist., mkd. 1/4 S BT  
A Cedar 20" dia., bears S.32°W., 24 lks. dist., mkd. 1/4 S BT.

Not Fd. DCSO, Oct. 1967 (added 3/27/2017), C.S. File 54/53-19 Fd 2 stumps but no evidence. Stumps hit good for bearing & dist. Also pretty good dist. for call 11|12 not fd logged & burnt.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #1018, surveyed June/Aug. 1980 (DCSO records Vol. 44 Page(s) 16978)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 32 S R 6 W  
1/4  $\frac{S\ 12}{S\ 13}$   
1980

from which  
A Cedar 9" dia., bears N.77 3/4°E., 34 1/2 lks., mkd. 1/4 S12 BT.  
A Fir 15" dia., bears S.22°W., 59 lks., mkd. 1/4 S13 BT.

Fd. Ok by Lloyd Smith, March 1997 - M124-46  
Found OK by K. Hoffine, Nov. 2002 - M141-34

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records Vol. 59 Page(s) 23766-7)

-----  
The 1/4 sec. cor. of secs. 12 and 13, reported by Aanrud in 1980, monumented with an iron post, 2 1/2" dia., firmly set, projecting 12" above the ground, in a collar of stone, with brass cap (properly) mkd.  
from which bearing trees reported by Aanrud  
A cedar, 17" dia., bears N.77 3/4°E., 22.4 ft., with a healed blaze. (Record, 22.8 ft.)  
A fir, 25" dia., bears S.22°W., 38.4 ft., with a healed blaze. (Record, 38.9 ft.)