

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & S. 25, T32-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by WH Byars, Deputy Surveyor under contract # 420  
survey dated Sept 16 1881 (DCSO records Vol 20 Pages 8707-8)

-----  
Marked a Fir, 38" dia., for the ¼ sec. cor. marked W. side ¼  
S, from which

A Laurel 10" dia., bears N.60°E., 36 lks. mkd. ¼ S BT.

A Chinquapin 6" dia., bears S.75°W., 38 lks. mkd. ¼ S BT.

-----  
Douglas Co. Surveyors Office - John M. Powell, Frank Jones,  
Joe Brady, crew - November 1967 - C.S. File 54/36-94

-----  
Found - 38" D.Fir Corner tree, now 43", faint bark scribe  
visible on West side, 1/ S

No trace of Laurel or Chinquapin BT.

Set Brass cap on W. side of Corner tree mkd:

County Surveyors Office

R T 32 S R

8 ¼ S 25 | S 30 7

W 1967 W

New BTs -12" D.Fir N.7°W., 56.4 ft. mkd. ¼ S25 CS BT.

13" D.Fir N.35°E., 84.5 ft. mkd. ¼ S30 CS BT.

-----  
Fd. OK, October 1990, M 111-4

-----  
BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor  
under Group No. 2179, surveyed July/Nov. 2007 - (DCSO  
records, Vol. 55 Page(s) 21600-01)

-----  
The ¼ sec. cor. of secs. 25 and 30, on the W. bdy. of the  
Tp., perpetuated by the Douglas County Surveyor's Office, in  
1967, monumented with the remains of the original cor. tree,  
a sawed fir stump, 48" dia., no scribe marks visible, from  
which the remains of BTs mkd., and a reference monument set,  
by the Douglas County Surveyor's Office, in 1967:

A sawed fir stump, 25" dia., bears N.35°E., 84.1 ft., with  
a healed blaze.

A fir, 22" dia. bears N.10°W. 57.9 ft. with a healed blaze

An iron post, 1" dia., firmly set along the W. side of the  
cor. stump, projecting 10" above the ground, bears  
N.77°34'45"W., 1.97 ft., with brass cap mkd. R8W T32S  
R7W ¼ S25 S30 1967.

and a new bearing tree

A fir, 14" dia., bears N.18°E., 23.9 ft., mkd. ¼ S30 BT.

-----  
DCSO-GIS Corner visitation - 1/28/2004 - Typed: 2/10/2011 -  
C.S. File 67/33-1

-----  
Monument - 1¼" IP/BC

Comment - needs rehab