

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8761-62)

Set an Oak post, 4 ft. long, 4" sq., 22" in the ground mkd. 1/4 S on N. side for the 1/4 sec. cor., from which:
A Laurel 7" dia., bears S.54°W., 47 lks. mkd. 1/4 S BT.
An Alder 12" dia., bears N.5°E., 37 lks. mkd. 1/4 S BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #'s 350 and 960, surveyed Aug/Sept. 1978 (DCSO records Vol. 42 Page(s) 16505)

The 1/4 sec. cor., determined at record distance from the remains of the original bearing trees:

An Alder 24" dia., bears N.21°W., 37 lks., with healed blaze. (Rec. N.5°E.)
A Madrone root crown bears S.54°W., 47 lks., no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S R 7 W
1/4 S 7
S 18
1978

from which new bearing trees:

A Live Oak 8" dia., bears N.55 1/2°W., 68 lks. mkd. 1/4 S7 BT.
A Fir 13" dia., bears S.7 1/4°E., 40 lks. mkd. 1/4 S18 BT.

Ron Quimby - 10/2013 - C.S. File 65/80-29

Condition Report only

Found - 1978 BLM brass cap (properly mkd)
10" Live Oak N.55 1/2°W., 44.9 ft., healed face.
16" Fir S.7°E., 26.4 ft., healed face.

Note - Set alum post 2 ft. east & west of corner.
Area burnt 7/2013