

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8749)

-----  
Set a Fir post, 4 ft. long, 24" in the ground, 4" sq., marked ¼ S for ¼ sec. cor., from which  
A Fir 16" dia., bears East, 28 lks. mkd. ¼ S BT.  
A Fir 24" dia., bears S.28°W., 34 lks. mkd. ¼ S BT.

Survey by Lorne Swearingen - Wit: R.Harris and M. Larson - For: Robert Dollar Co. - April 15, 1960 - C.S. File 51/63-2

-----  
Corner found to be in very poor condition. Both orig. BTs had fallen over but the scribing was still visible. I marked the corner as follows:  
A 1¼" (O.D.) Iron pipe driven 20" in the ground for the corner.  
New BTs -12" Cedar S.89½°W., 33.7 ft., was referenced and scribed "S8 ¼ S 4186 BT."  
6" Cedar N.61½°E., 13.1 ft. scribed S9 ¼ S 4186 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - November 1967 - C.S. File 54/36-138

-----  
Found - No trace of 1¼" Iron pipe.  
12" now 13" Cedar S.89½°W., 33.7 ft. mkd. scribe visible "S8 ¼ S 4186 BT"  
6" Cedar, now down, N.61½°E., 13.1 ft. scribe visible "S9 ¼ S 4186 BT"  
Area logged, pipe evidently pushed out.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 32 S R 7 W  
¼ S 8 | S 9  
1967  
New BT - 13" Cedar N.38°E., 76.8 ft. mkd. ¼ S9 CS BT.