

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION S C for Secs. 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8703 and Page 8733)

-----  
Set Fir post, 4½ ft. long, 4" sq., and 20" in the ground, for S Cor. to Secs. 33 and 34, from which  
A Cedar 12" dia., bears N.55°E., 56 lks. dist. mkd. S C T32S R7W S34 BT.  
A Fir 28" dia., bears N.75°W., 34 lks. dist., mkd. S C T32S R7W S33 BT.  
A Cedar 24" dia., bears S.20°E., 34 lks. dist., mkd. S C T33S R7W S4 BT.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - March/Aug. 1954 - C.S. File 41/301

-----  
Determined at record bearing and distance from the only extant original bearing tree.  
At the Corner point  
Set an Iron pipe, 3 ft. long, 2" dia., 28" in the ground, mkd. RS33.  
From which an original bearing tree  
An Incense Cedar 24" dia., bears N.55°E., 56 lks. dist., with the scribe marks S34 SC visible.  
New BT - An Incense Cedar 14" dia., bears N.34½°W., 15½ lks. dist., mkd. T32S R7W S33 SC RS33 BT.

Fd. OK, DCSO, J.Powell, Dec. 5, 1967, C.S. File 54/36-101

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #845, surveyed April/Nov. 1975 (DCSO records Vol. 41 Page(s) 16270)

-----  
The standard cor. of secs. 33 and 34, perpetuated and recorded by Price, in 1954, monumented with an iron pipe 2" dia., firmly set, projecting 6" above ground, with brass washer mkd. RS 33, from which the remaining original bearing tree:  
A Cedar 24" dia., bears N.55°E., 56 lks. dist., with healed blaze.  
and a bearing tree mkd. by Price  
A Cedar 18" dia., bears N.34½°W., 15½ lks. dist., with healed blaze.  
At the corner point  
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, directly over iron pipe, with brass cap marked  
(Cont. Next Page)

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION S C for Secs. 33 and 34 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>S C T 32 S R 7 W <u>S 33   S 34</u> 1975</p>
<p>Found OK by R. Templin, July 1995 - M122-53</p>
<p>Ron Quimby - Crew: N. Fromdahl &amp; D. Manring - 9/2014 - C.S. File 65/86-18</p> <p>-----</p> <p>Condition report only Found - BLM brass cap 26" Cedar stump (7' tall) N.34°W. 10.2 ft good scar. 16" Cedar stump (6' tall) N.48°E. 19.0 ft good scar. 27" cedar stump (6' tall) N.55°E. 37.0 ft good scar. Note - Area badly burnt 2013. Compass decl. 15½°E.</p>
<p>Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 4-21-2025 - C.S. File 67/60-26</p> <p>-----</p> <p>Found - BLM brass cap, up 1". S.C. T32S R7W <u>S33   S34</u> 1975</p> <p>26" Cedar stump 7' tall N.34°W. 10.2 ft. Good scar 16" Cedar stump 6' tall N.48°E. 19.0 ft. Good scar 27" Cedar stump 6' tall N.55°E. 37.0 ft. Good scar Metal post ± 2.0 ft east. Notes - Mon. on steep draw. Bank facing N.N.W. and 15'± North of gravel road. Compass decl. 14½°E. OGRS COORDINATE SYSTEM COTTAGE GROVE-CANYONVILLE ZONE N. -34011.168 E. 112344.688</p>