

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8734)

-----  
Set Fir post, 4 ft. long, 4" sq., 22" in the ground for the cor. to secs. 27, 28, 33 and 34 marked T32S R7W S27 on NE.; S34 on SE.; S33 on SW.; and S28 on NW.; also one notch on S. and 3 on E. angles, from which

A Pine 16" dia., bears N.60°E., 30 lks. mkd. T32S R7W S27 BT.

A Fir 24" dia., bears S.8°E., 20 lks. mkd. T32S R7W S34 BT.

A Fir 18" dia., bears S.15°W., 15 lks. mkd. T32S R7W S33 BT.

A Fir 8" dia., bears N.60°W., 57 lks. mkd. T32S R7W S28 BT.

Survey by Milner L. Larsen, RE #3642 - Aug. 11, 1954 - C.S. File 41/289

-----  
Found - A 12" Fir bearing N.60°W., 57 lks., mkd. T32S R7W S28 BT. This tree later destroyed in road construction. From this tree, I set the cor., A 2" Iron pipe 30" long, 24" in the ground.  
Fir 24" dia., bears N.64½°E., 92.4 ft. mkd. 3642 BT.  
Fir 30" dia., bears S.42°E., 117.1 ft. mkd. 3642 BT.  
Tan Oak 6" dia., bears S.54½°W., 119.6 ft. mkd. 3642 BT.  
Tan Oak 5" dia., bears N.42°W. 86.1 ft. mkd. 3642 BT.

Fd. OK, DCSO, J.Powell, Dec. 4, 1967, C.S. File 54/36-103

Cor. referenced out for road work, DCSO, J.Powell, May 1972 -C.S. File 59/30 - see below

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - M.W. Cline, crew -Aug. 22, 1977 - C.S. File 59/38-19

-----  
Found - No trace of orig. post or 2" I.P. set by Larsen, 1954  
No trace of original bearing trees.  
A 30" Fir now 32" stump, with scribing BT and other illegible scribing visible on an unhealed double blaze. Found PK nail in stump.  
5/8 I.Rod firmly set, 10.3 ft. N.42°W., of the BT stump (this cor. was referenced out for road construction in 1972 by Powell, DCSO)

(Cont. Next Page)

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

We establish the corner at N.42°W., 106.8 ft. from the found  
5/8" I.Rod.

Also found -

A 32" D.Fir stump, previously described, bears  
S.42°E., 117.1 ft.

A 6" Tan Oak now an 8" snag, with scribing "3642 BT"  
visible on unhealed blaze, bears S.54½°W., 120.9  
ft. (Rec. S.54½°W. 119.6 ft.)

A 5" now 10" Tan Oak with scribing "3642 BT" visible  
on unhealed blaze, bears N.42°W., 87.0 ft. (Rec.  
N.42°W., 86.1 ft.)

At the corner point, we set: A 1"x30" I.Pipe 20" in the  
ground with mound of stone to top, with brass cap attached  
marked:

Douglas County Surveyor

T 32 S R 7W

S 28 | S 27

S 33 | S 34

1977

New BTs -16" D.Fir scribed "T32S R7W S33 CS BT" on a double  
blaze, bears S.44°W., 97.8 ft.

18" Live Oak scribed "T32S R7W S34 CS BT" on a double  
blaze, bears S.81°E., 76.6 ft.

Corner located 31 ft. West of the centerline of Cow Creek  
Access Road and one foot East of a steel fence post with  
survey marker witness sign attached.

Fd. OK, by M. Smalley, July 1993, M 117-48

Found OK by R. Templin, July 1995 - M122-53

Bruce Shaner - For: Roseburg Resources - March 2002 - M137-35  
& C.S. File 65/42-13

Found - 2" iron pipe with 2½" brass cap (properly mkd.),  
from which a:

10" Tan Oak BT, face rotten, bears N.42°W., 87.0 ft.

28" D.Fir BT, face overgrown, bears S.44°W. 97.8 ft.

20" Live Oak BT, face overgrown, bears S.78°E.,  
(rec. S.81°E.) 75.5 ft. (Rec. 76.6 ft.)

6' steel post bears N.75°W., 1.5 ft.

New - 6" D.Fir BT, scribed "S27 BT" bears N.16°E. 15.0 ft.

6 ft. steel fence post bears South 1.0 ft.

Note - Corner is 31 ft. West of centerline of Cow Creek Rd.