

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8740)

Set a Fir post, 4 ft. long, 4" in dia., 20" in the ground for the cor. to secs. 3, 4, 9 and 10 marked T32S R7W S3 on NE.; S10 on SE.; S0 on SW.; and S4 on NW. angles, with 5 notches on S. and 3 on E. of same, from which:

- A Fir 16" dia., bears N.32°E., 25 lks. mkd. T32S R7W S3 BT
- A Fir 16" dia., bears S.70°E., 20 lks. mkd. T32S R7W S10BT
- A Fir 20" dia., bears S.54°W., 20 lks. mkd. T32S R7W S9 BT
- A Laurel 10" dia., bears N.34°W., 26 lks. mkd. T32S R7W S4 BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #543, surveyed June, 1964 (DCSO records Vol. 33 Page(s) 13653)

The sec. cor., determined at record bearing and distance from the remaining original bearing trees:

- A Fir 20" dia., bears N.32°E., 25 lks. with a healed blaze
- A Fir 23" dia., bears S.70°E., 20 lks. mkd. T 2S 7 BT on bark blaze.
- A Fir 27" dia., bears S.54°W., 20 lks. mkd. T32SR7W S9 on bark blaze.
- A stump hole bears N.34°W., 26 lks. dist.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 22 ins. in the ground, with brass cap marked

T 32 S R 7 W
S 4 | S 3
S 9 | S 10
1964

from which a new bearing tree:

- A Fir 27" dia., bears N.81°W., 58 lks. mkd. T32S R7W S4 BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Nov. 1967 - C.S. File 54/36-150

- Found - 1964 U.S. Cadastral brass cap.
32" D.Fir N.81°W., 38.3 ft., pitched over scribe marks visible.
Orig. 16" D.Fir, now dead, N.32°E., 16.5 ft. shows scar.
Orig. 16" D.Fir, now dead, S.70°E., 13.2 ft. faint scribing visible, BT
Orig. 20" D.Fir now dead, S.54°W., 13.2 ft., scribe visible T32S R7W S9 BT.

(Cont. Next Page)

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

New BTs - 8" D.Fir S.48°E., 20.8 ft. mkd. T32S R7W S10 CS BT.
22" D.Fir N.11½°E., 42.3 ft. mkd. T32S R7W S3 CS BT.
13" D.Fir S.30°W., mkd. T32S R7W S9 CS BT.

Survey by Bruce A. Shaner, L.S. #430 - April 17, 1989 - C.S.
File 63/85-12

Found - 3¼" U.S. BLM brass cap on a 2½" x 32" galv. I.P.
32" D.Fir BT, now a stump, with all scribes visible
and well pitched over, bears N.81°W., 38.3 ft.
12" D.Fir BT, now snag in rotten condition, (was
16") scribes rotted off, bears N.32°E., 16.5 ft.
16" D.Fir BT, now rotten stump, scribes gone, bears
S.70°E., 13.9 ft. (Rec. 13.2 ft.)
20" D.Fir BT, now 10 ft. high snag, scribes were
burnt off, so I rescribed: "T32S R7W S9 BT" bears
S.54°W., 13.2 ft.
8" D.Fir BT, S.48°E., 20.8 ft. is now gone.
22" D.Fir BT, now stump, with scribes gone, I
rescribed "T32SR7W S3 BT" bears N.11½°E., 40.6
ft. (Rec. 42.3 ft.)
16" D.Fir BT now stump with scribes visible, bears
S.30°W., 28.4 ft. (Rec. 30.0 ft.)

Corner area was recently logged over. Prior to logging, I
tied all bearing trees from existing brass cap and made
additional references, then removed brass cap. After
logging, I replaced brass cap in exactly same place and
rescribed some trees as necessary and added new one. All
green trees now gone.

New BT - 36" D.Fir stump BT, I scribed "T32S R7W S10 BT",
bears S.30°E., 32.5 ft. Put fence post, steel,
and tag alongside brass cap.

Corner lies approx. 150 ft. North of landing on main spur
road.

Fd. BC & accessories by G Neitsch, 11/2022 - M181-49