

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8738)

-----  
Set a Fir post 4 ft. long, 4" sq., 24" in the ground marked ¼ S on N. side for the ¼ sec. cor., from which  
A Fir 10" dia., bears S.65°E., 9 lks. dist. mkd. ¼ S BT.  
A Fir 60" dia., bears N.75°W., 56 lks. mkd. ¼ S BT.

Survey by Norman D. Price, For: Dollar and Patterson Lumber Co. - Sept. 1954/April 1955 - C.S. File 42/373

-----  
Determined at the record bearing and distances from each original bearing tree.  
At the corner point  
Set an Iron pipe 3 ft. long, 1½" dia., 28" in the ground, mkd. RS33; from which the original bearing trees:  
A D.Fir 50" dia., bears N.75°W., 56 lks. dist., mkd. on bark ¼ S BT.  
A D.Fir 16" dia., bears S.65°E., 9 lks. dist., with blaze healed.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Nov. 3-6, 1967 - C.S. File 54/36-89

-----  
Found - 1½" Iron pipe, out of ground, pulled when SE BT fell.  
Orig. 50" D.Fir now 50", N.75°W., 37.0 ft. bark scribe visible ¼ S  
Orig. 16" D.Fir now down, S.65°E., 5.9 ft.  
Reset 1½" Iron pipe at ¼ corner from NW bearing tree.  
New BT - 7" Chinquapin S.76°W., 17.1 ft. mkd. ¼ S22 CS BT.