

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Pg 8713)

Set a Pine post, 4 ft. long, 5" dia., 18" in the ground, marked ¼ S on W. side for the ¼ sec. cor., from which
A Pine 36" dia., bears S.45°E., 24 lks. dist., mkd. ¼ S BT
A Pine 40" dia., bears S.28°W., 20 lks. dist., mkd. ¼ S BT

Not fd. However fd 12" D.Fir S.82½°E., 36.4' scribed 3(?)42 BT. This work done approx. 1955 by ring count. No record of said tree, by JP 3/1968 - C.S. 54/36-124 (added 10/12/2016)

Survey by Ronald Brandt, L.S. #841 - For: Robert Dollar Co. -April 1980 - C.S. File 58/125N and M 83-29

Set 1" x 30" Iron pipe.
BTs - 6" D.Fir bears S.36°W., 17.62 ft. mkd. "¼ PS841 BT".
24" Madrone stump, bears East, 0.1 ft. mkd. "¼ PS841 BT
8" D.Fir bears S.82°39'E., 36.40 ft., a reference tree from the Robert Dollar Co.'s 1954 staff compass survey.
16" D.Fir bears S.82°E., 33.73 ft. with scribe marks "3642 BT" visible on a previously opened face.
This corner situated in an old burn area and could not find any evidence of original bearing trees. The ¼ corner was re-established at the single proportion point.

BLM Dependent resurvey by Stephan L. Barott, Cadastral Surveyor (Forest Service, USDA) under Group #1995, surveyed April/Nov. 2002 - (DCSO records Vol. 54 Page(s) 21153-4)

The ¼ sec. cor. of secs. 35 & 36, reestablished at proportionate measurement by Brandt in 1980. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron pipe, 1" dia., firmly set, projecting 1" above the ground, from which the remains of bearing trees mkd. by Brandt
A madrone stump, 18" dia., bears East, 0.1 ft. to face, with scribe marks ¼ PS841 BT visible on an open blaze.
A fir stump, 18" dia., bears S.36¼°W., 18.0 ft., with a healed blaze.
and the remains of BTs mkd. by person(s) unknown, reported by Brandt
A fir stump, 19" dia., bears S.85½°E., 35.2 ft. dist., with no marks visible.
A fir stump, 17" dia., bears S.82°E., 33.6 ft., with a healed blaze.

At the corner point continued next page

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set a stainless steel post, 28" long, 2½" dia., 28" in the ground, directly over the iron pipe, with brass cap mkd.

T32S R7W

¼

S 35 | S 36

2002

from which new bearing trees

A fir, 9" dia., bears N.20½°E., 30.2 ft., mkd. ¼ S36 BT.

A fir, 9" dia., bears N.80¼°W., 16.7 ft., mkd. ¼ S35 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

Deposit a magnet, in a white plastic case, at the base of the stainless steel post.

From this point, an unrecorded iron pipe, 1" dia., firmly set, projecting 4" above ground, bears S.89¾°W., 2.9 ft.

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 8/2014 - C.S.
File 65/86-12

Found - Brass cap & IP removed, fd magnet & plastic case.

12" D.Fir N.20½°E., 30.2 ft. good scar.

12 D.Fir N.80°W., 16.7 ft. good scar.

1" Iron pipe S.89°W., 2.9 ft.

Madrone stump East. East 0.1 ft. (badly burnt)

18" Fir stump S.36°W., 18.0 ft. (badly burnt)

19" Fir stump S.85½°E., 35.2

17" Fir stump S.82°E., 33.6 healed blaze.

New - A 5/8"x30" I.Rod with yellow plastic cap set over magnet @ record dist. from BTs & Fd. I.pipe.

8" madrone S.53°E., 12.3 ft. scribed ¼ S36 BT.

Note - Area burnt in Aug. 2013. Corner lies approx 40' north of road.

Compass decl. 15½°E.