

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 19 Page(s) 8024)

-----  
 Set a Cedar post 4½ ft. long, 18" in the ground, 4" sq., with one notch on E. and 5 on W. cor. marked T31S R7W S36 on NE. face; T32S S1 on SE. face; S2 on SW. face; S35 on NW. face; from which

- A Fir 36" dia., bears N.80°E., 48 lks. dist., mkd. T31S R7W S36 BT.
- A Fir 10" dia., bears S.20°E., 12 lks. dist., mkd. T32S R7W S1 BT.
- A Fir 12" dia., bears S.60°W., 15 lks. dist., mkd. T32S R7W S2 BT.
- A Fir 14" dia., bears N.45°W., 44 lks. dist., mkd. T31S R7W S35 BT.

Cor. Fd. and used by Byars in his 1882 survey, (DCSO records, Vol. 19 Page 8035)

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531, surveyed Oct. 1963/June 1964 (DCSO records Vol. 33 Page(s) 13616-17)

-----  
 The Sec. Cor., recorded and remonumented in 1961 by Johnstone, with an iron pipe 1" dia., 8" above ground, firmly set. The original cedar corner post, 4 ft. long, 4" sq., with scribe marks S R7W S still legible, is found lying alongside. From the iron pipe, the original bearing trees:

- A Fir 36" dia., bears N.80°E., 50 lks. dist., (48 lks. to face) mkd. T37S B on a bark blaze. (Rec. dist., 48 lks.)
- A Fir 14" dia., bears S.20°E., 12 lks. dist., mkd. with a healed blaze.
- A Fir 15" dia., bears S.60°W., 15 lks. dist., mkd. T32S R7W S2 on bark blaze.
- A Fir stump hole bears N.45°W., 44 lks. dist. and a bearing tree mkd. by Johnstone:

A Fir 13" dia., bears N.9°W., 32 lks. dist., mkd. S35 T31S R7W BT.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 23 ins. in the ground, with brass cap marked

T 31	S R 7 W
S 35	S 36
S 2	S 1
T 32	S R 7 W

1964

Reset the iron pipe and cedar post alongside the iron post.

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; and 35 & 36, T31-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

(Note: Search by DCSO, could find no recorded survey or corner visit by Johnstone in 1961. Per Jean Crawford and Cody Bliss) (VL)

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #1086, surveyed April/June 1982 - (DCSO records Vol. 46 Page(s) 17561)

-----  
The Sec. Cor., monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground, with 1964 brass cap. from which the remains of the original bearing trees:

A sawed Fir stump 37" dia., bears N.80°E., 50 lks. dist., no marks visible.

A root hole bears S.20°E., 12 lks. dist., with a down Fir alongside, 18" dia., with healed blaze.

A Fir 16" dia., bears S.60°W., 15 lks. dist., with healed blaze.

and a bearing tree mkd. by Johnstone in 1969:

A Fir 15" dia., bears N.9°W., 32 lks. dist., with healed blaze.

and a new bearing tree:

A Fir 15" dia., bears S.17°E., 122 lks. dist., mkd. T32S R7W S1 BT.

Survey by Mark Smalley, Roseburg Forest Products, July 12, 1994 - C.S file 63/154-16

-----  
FOUND - 1964 BCIP

17" Fir, N.9°W. 21.1 ft., good healed face

36" Fir, N.80°E. 31.7 ft., O.B.T

14" Fir, S.20°E., 7.9 ft., down, O.B.T

16" Fir, S.60°W., 9.9 ft., good healed face, O.B.T

20" Fir, N.17°W., 80.52 ft., good healed face, no record.

New BT - 10" Cedar, S.79°W., 23.3 ft., scribed "S2 BT"

Corner is 200 ft. East of 31-7-25.1 road

DCSO-GIS Corner visitation - 2/18/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

-----  
Monument - 2.5" IP/BC

Comment - ok