

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8716)

-----  
Set a Yew post, 4 ft. long, 4" dia., 18" in the ground, marked  $\frac{1}{4}$  S on N. face, for the  $\frac{1}{4}$  sec. cor., from which  
A Fir 30" dia., bears North, 6 lks. dist. mkd.  $\frac{1}{4}$  S BT.  
A Cedar 10" dia., bears S.30°E., 36 lks. dist., mkd.  $\frac{1}{4}$  S BT.

Douglas Co Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - March 11, 1970 - C.S. 54/36-109

-----  
Found - Orig. 30" now 40" Fir, North 4.0 ft., down, stump in place, "BT" bark scribe.

No trace or orig. BT to SE due to roadway to creek.  
Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 7 W

$\frac{1}{4}$   $\frac{S}{S}$   $\frac{24}{25}$

1970

New BTs -50" D.Fir S.5°E., 70.8 ft. mkd. " $\frac{1}{4}$  S25 CS BT"

30" D.Fir N.88°W., 9.8 ft. mkd. " $\frac{1}{4}$  S24 CS BT"

This corner lies under log of a BT, approx. 60 ft. East of old logging road. Best route to corner,  $1\frac{1}{4}$  miles from Robert Dollar Logging Road at junction of Totten Creek.