

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8632)

Set ¼ sec. post, from which
A Laurel 10" dia., bears N.54°W., 6 lks. dist.
A Laurel 12" dia., bears S.73°E., 10 lks. dist.

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1861 (DCSO records Vol. 20 Page(s) 8659)

Not being able to find old cor. or witness trees, Set a Laurel post, 4 ft. long, 4" dia., 20" in ground, mkd. ¼ S on W. side for the ¼ sec. cor., from which
A Fir 36" dia., bears S.48°E., 45 lks. dist., mkd. ¼ S BT
A Fir 38" dia., bears N.52°W., 30 lks. dist., mkd. ¼ S BT

Not Fd. by John Powell, DCSO 10/1967 (added 3/28/2017) C.S. File 54/53-20 - Fd. burnt stob of SE(BT?) also Byars notch in bark below missing face. No scribe, good call distance. Location tag at approx cor + on ridge top.

BLM resurvey by G. Steven Popken, & James J. Carlson, under Group #851. Surveyed Sept. 1975/June 1976 (DCSO records Vol. 37 Page 15312)

Point for the ¼ sec. cor. of secs.19 and 24, at proportionate distance; there is no remaining evidence of the original cor. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked

T 32 S
1/4
R 7 W | R 6 W
S 24 | S 19
1976

from which
A Fir 13" dia., bears N.54½°E., 11½ lks., mkd. ¼ S19 BT.
A Fir 12" dia., bears N.75°W., 22½ lks., mkd. ¼ S24 BT.

Lloyd D. Smith - For: Oregon State Dept. of Forestry - Restored by James McIntosh, Engineer, Wit: David Buchholz and Christopher Hughes - March 13, 1978 - C.S. 58/164-2 & M 71-79

Found - Orig. Laurel post, remains of point found, from which a
36" Fir bears S.48°E., 45 lks., now 52" x 25 ft. high burnt and shattered snag in place, 48 lks. to center, exposed axe work at top of face and chaining notch at bottom of face. cont. next pg

Alias	Description
Alias	Description
Alias	Description
Alias	Description

38" Fir bears N.52°W., 30 lks., now stump hole with portions of roots remaining.
Set 1½" x 36" galv. I.P. with 3" bronze cap mkd. "Oregon State Board of Forestry T32S ¼ R7W R6W S24 S19 1978 RS1101", 34" in ground and from which a:
27" Fir bears S.35°W., 23.8 ft. to face; scribed ¼ S24 BT RS1101.
10" Madrone bears S.72°E., 21.1 ft. to face; scribed ¼ S19 BT RS1101.
Set 4" x 4" x 72" white painted cedar post N.58°E., 2.9 ft. from corner pipe. OSFD metal location poster on 11" madrone. BLM pipe and cap, N.06°53'W., 21.3 ft. to be obliterated by BLM.

BLM survey by Lynn M. Roseberry, Cadastral Surveyor, under Group #884, surveyed June 1979 (DCSO records Vol. 41 Page(s) 16233)

The ¼ sec. cor., perpetuated and recorded by Lloyd Smith in 1978, monumented with a galv. iron pipe 1½" dia., firmly set, projecting 2" above ground, with properly mkd. bronze cap., from which the remains of bearing trees mkd. by Byars:

A burned and shattered Fir stump 52" dia., bears S.48°E., 48 lks. dist., with axe work visible at top and a chaining notch visible at bottom of opened blaze. The center of blaze has been removed. (Rec. 45 lks.)

A burned out root crown, approx. 48" dia., bears N.52°W., 30 lks. dist.

and bearing trees mkd. by Smith:

A Madrone 10" dia., bears S.72°E., 32 lks. dist., with scribe marks ¼ S19 BT RS1101 visible on open blaze.

A Fir 28" dia., bears S.35°W., 37 lks. dist. with scribe marks ¼ S24 BT RS1101 visible on opened blaze.

From this point, the ¼ sec. cor. of secs. 19 and 24, erroneously reestablished by Popken and Carlson in 1976, bears N.6°53'W., 0.32 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, mkd. and witnessed as described in the official record of the 1975-76 resurvey.

I remove the iron post, and destroy the scribe marks on the bearing tree.