

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8633)</p> <p>-----</p> <p>Set ¼ sec. post on steep N. slope, from which A Fir 20" dia., bears N.57°E., 58 lks. dist. A Fir 18" dia., bears S.82°W., 34 lks. dist.</p>					
<p>GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1861 (DCSO records Vol. 20 Page(s) 8660)</p> <p>-----</p> <p>Set Cedar post, 4 ft. long, 4" sq., mkd. ¼ S on W. side, 18" in ground for the ¼ sec. cor., from which A Fir 24" dia., bears S.22°E., 50 lks. dist. mkd. ¼ S BT. A Fir 30" dia., bears S.35°W., 37 lks. dist. mkd. ¼ S BT.</p>					
<p>Not Fd. by John Powell, DCSO 10/1967 (added 3/28/2017) C.S. File 54/53-20 - No trace of BTs good line &amp; paced in calls from north &amp; south. Face on one tree opened 34 yrs old. Nothing on this tree.</p>					
<p>BLM resurvey by G. Steven Popken, Cadastral Surveyor &amp; James J. Carlson, under Group #884. Surveyed Sept. 1975/June 1976 (DCSO records Vol. 37 Page(s) 15314)</p> <p>-----</p> <p>Point for the ¼ sec. cor. at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked</p> <table border="0"><tr><td>T 32 S</td></tr><tr><td>1/4</td></tr><tr><td>R 7 W   R 6 W</td></tr><tr><td>S 13   S 18</td></tr><tr><td>1976</td></tr></table> <p>from which A Fir 13" dia., bears N.55°E., 17½ lks. mkd. ¼ S18 BT. A Fir 10" dia., bears S.65°W., 48 lks. mkd. ¼ S13 BT.</p>	T 32 S	1/4	R 7 W   R 6 W	S 13   S 18	1976
T 32 S					
1/4					
R 7 W   R 6 W					
S 13   S 18					
1976					
<p>BLM Resurvey by Lynn Roseberry Cadastral Surveyor under Group #884 - Surveyed June 1979 (DCSO records Vol. 41 Pg) 16236)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner. From this point, the ¼ sec. cor. of secs.13 and 18, erroneously reestablished by Popken and Carlson in 1976, bears S.3°21'W., 0.18 chs., monumented with an iron post 2½" dia., firmly set, projecting 4" above ground, mkd. and witnessed as described in the official record of the 1975-76 resurvey. (Cont. Next Page)</p>					

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18 of T32-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

I remove the iron post, and at the true corner point  
Reset the iron post, 28" long, 2½" dia., 24" in the ground,  
with brass cap mkd. T 32 S

¼  
R 7 W | R 6 W  
S 13 | S 18  
1976  
1979

from which bearing trees mkd. by Popken and Carlson

A Fir 15" dia., bears S.58½°E., 15½ lks. dist., with  
scribe marks ¼ S18 BT visible on partially healed  
blaze.

A Fir 12" dia., bears S.49°W., 58 lks. dist., with scribe  
marks ¼ S13 BT visible on partially healed blaze.

BLM resurvey by Mark Dixon and Henry Hartley, Cadastral  
Surveyors, under Group #1337, surveyed July/Sept. 1989 (DCSO  
records Vol. 48 Page(s) 18561)

-----  
Point for the ¼ sec. cor. of secs. 13 and 18, at  
proportionate distance; there is no remaining evidence of the  
original corner.

From this point, the ¼ sec. cor. of secs. 13 and 18,  
erroneously corrected by Roseberry in 1979, bears  
N.16°33'30"E., 0.485 chs. dist., set, marked, and witnessed  
as described in the official record. Remove the iron post  
and at the true corner point

Reset the iron post, 28" long, 2½" dia., 24" in the ground  
with brass cap mkd. T 32 S

¼  
R 7 W | R 6 W  
S 13 | S 18  
1976  
1979  
1989

from which bearing trees mkd. by Popken and Carlson, and  
re-described by Roseberry

A Fir 16" dia., bears N.35°E., 47 lks. with healed blaze.

A Fir 13" dia., bears N.75 ¾°W., 30½ lks., with healed  
blaze.