

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18 only, (West)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8778-79)

-----  
Set a stone 18x12x10 ins., 12" in the ground for the cor. to secs. 7, 12, 13, and 18, marked with 4 notches on the South and 2 notches on the North corner of same, and from which  
A Fir 22" dia., bears N.80°E., 13 lks. dist. mkd. T32S R8W S7 BT.  
A Fir 15" dia., bears S.38°E., 38 lks. dist. mkd. T32S R8W S18 BT.  
A Fir 28" dia., bears S.28°W., 26 lks. dist. mkd. T32S R9W S13 BT.  
A Live Oak 6" dia., bears N.12°E., 63 lks. dist. mkd. T32S R9W S12 BT.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8845)

-----  
Intersect the old cor. of secs. 7, 12, 13, and 18, which is a basalt stone 18x12x10 ins., loosely set, mkd. and witnessed as described by the surveyor general, except for a discrepancy in the distance of the NE. bearing tree and that the SE. tree is dead. I change this cor. to refer to secs. 7 and 18 only and perpetuate it as follows: alongside the old cor.

Set an iron post 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 7 and 8, with brass cap mkd.

T32S  
S 7  
S 18  
R8W  
1917

from which  
A Fir 36" dia., bears N.80°E., 23 lks. dist. mkd. T32S R8W S7 BT (Old BT)  
A Fir 30" dia., bears S.82°E., 57 lks. dist., mkd. T32S R8W S18 BT (New BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - June 1967 - C.S. File 54/44-42

-----  
Found - 36" D.Fir, now down, N.80°E., 15.2 ft., scribe visible.  
30" now 36" D.Fir, S.82°E., 37.6 ft., shows good scar.  
RESET 1917 GLO brass cap, properly mkd. (BC found out of ground) (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18 only (West)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

New BT - 36" D.Fir N.70½°E., 57.3 ft. mkd. T32S R8W S7 CS BT  
 Corner lies in bottom of deep ravine, approx. 800.0 ft. S. of  
 Jeep road, location tag on road.

Douglas Co. Surveyors Office - Randall Smith and Stephen  
 Flause, crew - Dec. 13, 1992 - C.S. File 64/35-5

-----  
 Found - No evidence of original basalt stone or brass cap  
 monument of 1917 resurvey found.  
 No evidence of original BTs found.  
 1917 BT, a 30" dia., now a fallen and out of  
 position 39" DBH D.Fir with possible healed  
 blaze, the root hole of which bears S.82°E., 37.6  
 ft.  
 36" D.Fir now a 42" DBH D.Fir with a double blaze,  
 upper blaze is fully healed, lower blaze is  
 partially healed and shows illegible scribing,  
 bears N.70½°E., 57.3 ft.

Set monument at position determined from found 1917 resurvey  
 bearing tree root hole and 1967 BT (previously described)  
 Monument is a 2 3/8" dia. brass cap marked:

Douglas County Surveyors Office

	T 32 S	
R	S 7	R
9	S 18	8
W	1992	W

Brass cap on a 1¼" O.D. 32" I.P. set protruding 4" above  
 ground.

New BTs- 6" DBH Tan Oak scribed "X BT" on a double blaze,  
 bears N.22½°E., 40.6 ft.  
 8" DBH D.Fir scribed "T32S R8W S7 CS BT" on a double  
 blaze, bears N.39½°E., 68.3 ft.  
 5" DBH D.Fir scribed "X BT" on a double blaze. This  
 is a piston butt Fir the base of the vertical  
 portion of the trunk, bears S.52°E., 28.7 ft.  
 Corner lies in bottom of a steep ravine 800 ft. South of Jeep  
 road and 1,000 ft. West of BLM Rd. 32-9-14.4