

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 6; and 31, T31-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8102)

Set a stone 16x14x10 ins., 8" in the ground, marked ¼ on N. side for the ¼ sec. cor., from which
A Fir 30" dia., bears S.10°W., 12 lks. dist., mkd. ¼ S BT
A Fir 32" dia., bears N.30°W., 35 lks. dist. mkd. ¼ S BT.

Lorne Swearingen - Wit: Robert Harris and Milner Larson - Feb. 18, 1960 - C.S. File 51/68-1

This corner was found to be in poor condition.
The orig. BT in Sec.31 was felled in a clear cut logging operation. This tree had been barked scribed and the evidence of scribing visible before falling.
The orig. BT in sec. 6 remains standing but is a snag.
The original corner called for a stone, not found.
I Set a 1" (inner dia.) iron pipe driven 18" into the ground for the ¼ cor. for sec. 31, T31-8 and S. 6, T32-8.
Since the area to the North has been clear cut and not trees available to scribe:
A 40" D.Fir S.58°E., 39.7 ft. was referenced and scribed "S6 ¼S BT."
BT was referenced with a compass and chain.

Douglas Co. Surveyors Office - John M. Powell, and crew - Feb. 6, 1967 - C.S. file 54/36-80

Found - 1¼" Iron pipe at ¼ corner.
Orig. 30" Fir now stob, S.10°W., 7.9 ft.
30" Fir now stump, N.34°W., 23.1 ft., scribe visible, S31 ¼S BT (Rec. N.30°W.)
40" now 42" Fir S.58°E., 39.7 ft. scribed ¼
New BT - 8" Tan Oak N.31½°W., 64.0 ft. scribed ¼ S31 CS BT.
Corner lies 185.0 ft. East of creek.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21085)

The ¼ sec. cor. of secs. 6 & 31, recovered by Larson, in 1956, subsequently perpetuated & recorded by Swearingen, in 1960, subsequently perpetuated & recorded by the Douglas County Surveyors Office, in 1967; monumented with an iron pipe, 1¼" dia., firmly set, flush with the ground, from which the remains of the original bearing trees
A fir snag, 30" dia., bears S.10°W., 7.9 ft., with no visible marks.
continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 6; and 31, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A fir stump, 40" dia., bears N.34°W., 23.1 ft., axe mks. visible. (Record N.30°W.)
and a bearing tree mkd. by Swearingen
A fir, 45" dia., bears S.58°E., 39.7 ft., with illegible scribe marks visible on partially healed blaze.
and a bearing tree mkd. by the Douglas County Surveyor
A tan oak, 12" dia., bears N.31½°W., 63.4 ft., with healed blaze.
At the corner point
Set a stainless steel post, 28" long, 2½" dia., 16" in the ground, to solid rock, directly over the iron pipe, with brass cap mkd.
T 31 S R 8 W
¼ S 31
 S 6
 T 31 S
 2002
Deposit a magnet in a white plastic case at the base of the stainless steel post.

Fd. as per 2002 BLM resurvey by D. Edwards, 3/2011 - M162-26

BLM Dependent resurvey by Ernest Q. Lundeen, Cadastral Surveyor, under Group No. 2797, surveyed July/Aug 2015 - (DCSO records Vol. 58 Page(s) 23430-1)

The ¼ sec. cor. of secs. 6 & 31, monumented with a stainless steel post, 2½" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
A sawed fir stump, 35" dia., bears N.34°W., 23.1 ft., with a rotted healed blaze.
and a bearing tree mkd. by Swearingen in 1960
A fir, 47" dia., bears S.58°E., 39.7 ft., with scribe marks BT visible on partially healed blaze.
and a BT mkd. by the Douglas County Surveyor's Office in 1967
An oak, 12" dia., bears N.31½°W., 63.4 ft., with a healed blaze.