

PRIMARY CORNER DESCRIPTION Standard Sec. Cor. for 31 & 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8773)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground for the standard cor. to secs. 31 and 32, marked SC T32S R8W on N.; S32 on E.; S31 on W.; also 5 notches on E. and 1 notch on W., from which

- A Fir 22" dia., bears N.47°E., 24 lks. dist. mkd. SC T32S R8W S32 BT.
- A Fir 22" dia., bears S.27°W., 30 lks. dist. mkd. SC T33S R8W S6 BT.
- A Fir 20" dia., bears N.26°W., 30 lks. dist. mkd. SC T32S R8W S31 BT.

BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8858)

Find no evidence of the cor. post established for standard cor. of secs. 31 and 32. True point for cor. established from original bearing trees.

At exact cor. point,
Set a diorite stone 16x12x8 ins., 11" in the ground, mkd. SC on N., with 5 grooves on E. and 1 groove on W. face.

The old bearing trees being in poor condition, I obliterate markings on same and take new bearing trees as follows:

- A Fir 32" dia., bears N.47°E., 24 lks. dist., mkd. T32S R8W S32 SC BT.
- A Fir 26" dia., bears N.26°W., 30 lks. dist. mkd. T32S R8W S31 SC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-60

Found - No trace of corner stone.
32" D.Fir now snag, N.47°E., 15.8 ft., scribe visible "32S R8 S31 SC".

26" now 29" D.Fir N.26°W., 19.8 ft., shows good scar
Set Brass cap at cor. mkd: County Surveyors Office

	T 32 S	R
Doug.Co.	<u>S 31</u> <u>S 32</u>	8
Josp.Co.	S 5	W
	1968	

New BT - 7" D.Fir N.62°W., 56.2 ft. mkd. T32S R8W S31SCCS BT.
No other trees in area.

Corner lies approx. 200 ft. S. of ridge top, running E-W.