

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8773)

Set a stone 12x10x8 ins., 8" in the ground for the ¼ sec. cor. mkd. S C ¼ on N. side, from which

A Chinquapin 5" dia., bears N.15°E., 53 lks. dist. mkd. SC ¼ S BT.

A Fir 40" dia., bears S.80°W., 50 lks. dist. mkd. SC ¼ S BT.

BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8857)

The standard ¼ cor. of sec. 32, which is a granite stone 10x8x4 ins. above ground, firmly set, mkd. and witnessed as described by the surveyor general. The old bearing trees being in poor condition, I obliterate markings on same and take new trees as follows:

A Fir 8" dia., bears N.9°E., 5 lks. dist. mkd. SC ¼ S32 BT.

A Fir 6" dia., bears N.49°W., 18 lks. dist. mkd. SC ¼ S32 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 6, 1968 - C.S. File 54/65-59

Found - 10x8x4 stone at ¼ corner mkd. "¼" on N. face.
8" D.Fir now snag, N.9°E., 3.3 ft. scribe visible "S".

6" D.Fir now 7", N.49°E., 11.9 ft., shows good scar
Set Brass cap at cor. mkd:

County Surveyors Office
Douglas Co.
T32S S 32 R8
T33S Josp. Co. W
1968

New BT - 8" D.Fir N.18°E., 6.8 ft. mkd. ¼ S32 SC CS BT.
Corner lies on steep N. slope approx. 125.0 ft. E. of draw, NE-SW.