

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 266100

PRIMARY CORNER DESCRIPTION C.C. for Secs. 4 & 5 only, T33-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Norman D. Price, U.S. Surveyor, under Group #33, Surveyed May/June 1919 - C.S. File 64/76-1

At point of intersection (13.93 chs. West from standard cor. of secs. 32 and 33) Set a porphyry stone 16x10x8 ins., 11" in the ground, for closing cor. of secs. 4 and 5, mkd. CC on S.; with 4 grooves on E. and 2 grooves on W. face; from which
A Pine 18" dia., bears S.24°E., 90 lks. dist. mkd. T33S R8W S4 CC BT.
A Fir 16" dia., bears S.32°W., 64 lks. dist. mkd. T33S R8W S5 CC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 7, 1968 - C.S. File 54/65-68

Looked for, not found.
Cor. seems to fall in Rd. therefore no stone.
Also, 18" Pine is gone?
16" D.Fir S.32°W., 42.2 ft. is scribed for sec. 4, therefore bearing is wrong? dist?
Best do some checking on this cor.

True cor. not found. Record as not found.

J.M.P.
Jim.