

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Sec. Cor. for 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8772)

Set a stone 14x12x8 ins., 10" in the ground for the standard cor. to secs. 32 and 33 marked SC on N. face with 4 notches on E. and 2 notches on W. edges, from which
Pine 10" dia., bears N.14°E., 40 lks. dist. mkd. T32S R8W S33 BT.
Fir 12" dia., bears S.42°E., 40 lks. dist. mkd. T33S R8W S4 BT.
Fir 5" dia., bears N.64°W., 67 lks. dist. mkd. T32S R8W S32 BT.

BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8856-57)

The standard cor. of secs. 32 and 33, which is a granite stone, 12x8x4 ins., above ground, firmly set, mkd. and witnessed as described by the surveyor general. The old bearing trees being in poor condition, I obliterate markings on same and take new bearing trees as follows:
A Pine 30" dia., bears N.8°E., 50 lks. dist. mkd. T32S R8W S33 SC BT.
A Fir 12" dia., bears N.51½°W., 96 lks. dist. mkd. T32S R8W S32 SC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-63

Found - No trace of corner stone. (Sec. Cor. falls in shoulder of road.)
30" now 38" Pine, N.8°E., 33.0 ft., scribe visible, "3" "8" & others.
NW. tree falls in road.

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R
Doug. Co. S 32 | S 33
Josp. Co. S 4
T 33 S
1968

New BT - No trees available to the North.
12" D. Fir S.10°W., 64.1 ft. mkd. T33S R8W S4 SC CSBT
Corner lies on E. edge of road in mound of stone.

(Cont. Next Page)

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Cor. for Secs. 32 & 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Robert M. Thompson, LS #1358 - For: Boise Cascade
Tmber Lands of Oregon - Oct. 21. 1983 - M 95-33; C.S. File
58/275(n)

Found - 1968 DCS0 brass cap on 1" Galv. I.P. nearly
uprooted, lying on surface of road shoulder.
40" Sugar Pine N.8°E., 33.0 ft., face healed.
15" D.Fir S.10°W., 64.1 ft. (1968) face healed.
Since the hole remnant checks with the above BTs, I RESET the
monument therein flush with the surface, in northeasterly
shoulder of Rd. No. 34-8-1, northwesterly & southeasterly.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 6/16/2025 - C.S. File 67/60-41

Found - 2½" D.C.S.O. brass cap flush with surface (properly mdk).
Sawn, rotted 30"x5 ft sugar pine stump. N.8°E. 32.8 ft
(Rec 32.0 ft) blaze and scar. Add spike, top center.
30" D.Fir S.10°W. 64.0 ft (Rec 64.1 ft 1968) Fully
healed single blaze. Add 3½" mag nail, right side center.
New - 5/8"x30" Iron rod with D.C.S.O. plastic cap S.20°E.
20.6 ft. Set flush with ground.
5/8"x30" Iron rod with D.C.S.O. plastic cap N.85°W.
24.9 ft. Cap 10" above ground.
Iron rods are in easterly and westerly shoulder of
gravel road.

Notes - Mon is approx. 9 ft from gravel road.
Compass decl. 14½°E.
Trimble Geo XT Position
42°44'23.063"N.
123°39'29.454"W.