

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO rec Vol 21 Pg 8819)

A laurel, 6" dia., which I mkd ¼ S on W side for the ¼ sec. cor., and from which

A laurel, 6" dia., bears N.75°E., 26 lks., mkd: ¼ S BT.

A laurel, 8" dia., bears N.70°W., 42 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - April/May 1968 - C.S. 54/65-6 & C.S. 54/65-55 & C.S. 54/65-76

Reported as not found.

4/11/1968 - C.S. File 54/65-6

3 small laurels not found. Not to good of line, will look for again at later date when can get across Cow Creek directly from (cor. Secs.) 4, 5, 8, & 9

5/2/1968 C.S. File 54/65-55

Not fd: Found N-S blazes but no cor. 3 small laurels for BTs.

5/24/1968 C.S. File 54/65-76

Not found: 2nd time looked from this cor. from north & south. Left location tag for approx line & cor.

Richard Templin - For: Fruit Growers Supply 3/2002 - M139-74

At the proportionate position of the E ¼ cor. of sec. 8, I searched for orig. evidence of the 1883 corner w/no success At the proportionate position for the ¼ common to secs. 8 & 9, I set:

A 5/8"x30" iron rod, projecting 3", with a yellow plastic cap marked "TEMPLIN LS2359" from which I scribed BTs:

A Madrone, 8" dia scribed "¼ S8" "BT" bears N.60°E. 3.1 ft

A Tan Oak, 6" dia scribed "¼ S8" "BT" bears S.3°W. 16.4 ft

A Tan Oak, 8" dia., scribed "¼ S8" "BT" bears S.85°W., 22.2 ft

A D.Fir, 14" dia scribed "¼ S8" "BT" bears N.13°W. 12.6 ft
Corner lies East, 70 ft. from a K-tag on 12" Tan Oak on East side of road at landing.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21097-8)

The ¼ sec. cor of secs. 8 & 9, reestablished at proportionate measurement, and recorded by Templin, in 2002. There is no remaining evidence of the original cor., therefore this point is accepted as the corner; monumented with an iron rod, 5/8" dia., firmly set, projecting 6 ins. above the ground, with 1" dia. yellow plastic cap mkd. TEMPLIN LS 2359, (cont)

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which bearing trees mkd. by Templin
A madrone, 6" dia., bears N.54°E., 3.2 ft., with scribe marks ¼ S8 BT visible on partially healed double blaze. (This tree is erroneously marked.)
A live oak, 6" dia., bears S.5°W., 16.2 ft., with scribe marks ¼ S8 BT visible on partially healed double blaze.
A tan oak, 7" dia., bears S.85°W., 22.1 ft., with scribe marks ¼ S8 BT visible on partially healed double blaze.
A fir, 13" dia., bears N.13¾°W., 12.8 ft., with scribe marks ¼ S8 BT visible on partially healed double blaze.

At the corner point
Set a stainless steel post, 28" long, 2½" dia., directly over the iron rod, 24" in the ground, with brass cap mkd.

T32S R8W

¼
S 8 | S 9
2002

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Ron Quimby - For: Plum Creek Timber Co. - 4/2016 - M171-9

Found - BLM brass cap per 2004 USBLM DEP. Resurvey plat No 7141
7" Madrone N.54°E., 3.2' partially visible scribe
8" Live Oak S.05°W., 16.2' partially visible scribe
9" Tan Oak S.85°W., 22.1 partially visible scribe
16" Fir N.13¾°W., 12.8' fully healed blaze