

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract # 474 dated May 10, 1883 (DCSO records Vol. 21 Page(s) 8820)

Set a Fir post, 3 ft. long, 3" sq., 20" in the ground for the 1/4 sec. cor. marked 1/4 S on the N side, from which

A Fir, 72" dia., bears South, 8 lks., mkd: 1/4 S BT.

A Fir, 60" dia., bears N.10°W., 17 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - John Powell - 4/11/1968 - C.S. File 54/65-7

Reported as not found.

Found - Two very large Firs down & burnt.

Both tree stumps hit good for bearing & No evidence however approx. 60.00 ft. to the west found 4 scribed Laurels as follows (approx.) No cor. point.

5" Laurel N.35°E., 16.5 ft. bark scribed 1/4 E 3571 BT

5" Laurel S.87°E., 15.0 ft. bark scribed 1/4 E 3571 BT

5" Laurel S.75°W., 9.0 ft. bark scribed 1/4 E 3571 BT

12" Laurel N.10°E. 14.5 ft. bark scribed 1/4 E 3571 BT

This cor. is between 2 Fir stumps approx. bearing & dist. of orig. But appear to be too small. Cor. done approx. 6-55

(Note - 3571 is Harrison Munger's PE #, DCSO JC)

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/4/2002 - C.S. File 66/32-19

No corner monuments found.

No OBTs found.

Found 4 Madrone BTs as noted by Powell in 1968, C.S. 54/65. N.10°E., & S.75°W., BTs show faint bark scribing.

Other BTs standing snags bark is gone.

Note - Quadrant to the NE recently logged.

Ronald Quimby - For: Roseburg Resources Co. - March 2002 - M 139-64 A & B

Set - 5/8" x 30" I.R. w/ 2 1/2" alum. Cap marked:

ROSEBURG RESOURCES CO

1/4 $\frac{S \ 4}{S \ 9}$

LS 1654

2002

New BTs- 12" Fir N.2°W, 5.2 ft., scribed: T32S R8W 1/4 S4 BT

continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

16" Fir N.70°E, 6.9 ft., scribed: T32S R8W 1/4 S4 BT
14" Madrone S.37°W., 21.7 ft. scribed: T32S R8W 1/4
S9 BT.
8" Fir S.44°E, 11.7 ft. scribed: T32S R8W 1/4 S9 BT.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21099-100)

The ¼ sec. cor. of secs 4 & 9, reestablished at proportionate measurement and recorded by Quimby, in 2002. There is no remaining evidence of the original cor., therefore this point is accepted as the corner; monumented with an iron rod, 5/8" dia., firmly set, projecting 6" above the ground, with 2" dia. aluminum cap (properly) mkd. from which bearing trees mkd. by Quimby
A fir, 16" dia., bears N.70°E., 6.9 ft., with scribe marks T32S R8W ¼ S4 BT visible on partially healed blaze.
A fir, 8" dia., bears S.44°E., 11.7 ft., with scribe marks T32S R8W ¼ S9 BT visible on partially healed blaze.
A madrone, 14" dia bears S.37°W. 21.7 ft with scribe marks T32S R8W ¼ S9 BT visible on partially healed blaze.
A fir, 12" dia., bears N.2°W., 5.2 ft., with scribe marks T32S R8W ¼ S4 BT visible on partially healed blaze.