

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8099-8100)

Set a stone 16x14x14 ins., 8" in the ground mkd. with 3 notches on the E. and W. angles of same, for the corner to secs. 3, 4, 33 and 34, and from which

A Sugar Pine 20" dia., bears N.78°E., 55 lks. mkd. T31S R8W S34 BT.

A Sugar Pine 20" dia., bears S.75°E., 107 lks. mkd. T32S R8W S3 BT.

A Fir 30" dia., bears S.23°W., 36 lks. mkd. T32S R8W S4 BT

A Fir 22" dia. bears N.70°W., 42 lks. mkd. T31S R8W S33 BT

Douglas Co. Surveyors Office - John M. Powell, and crew - Jan. 1967 - C.S. File 54/36-71

Found - Orig. 30" now 51" D.Fir S.23°W., 23.8 ft., faint bark scribe "32 8 B"

Orig. 22" now (?)" D.Fir N.70°W., 27.7 ft. has been rescribed but pitched over.

Orig. 20" now (?)" S.Pine S.75°E., 70.6 ft., shows good scar.

Orig. 20" S.Pine, now dead, N.78°E., 36.3 ft., scribe visible "T31S R8 S34".

Stone, 3 v on E. and W. faces.

Also Iron pipe at section corner.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 8 W

S 33 | S 34

S 4 | S 3

T 32 S

Reblazed and rescribed:

51" D.Fir S.23°W., 23.8 ft. mkd. T32S R8W S4 CS BT

No trees in section 34.

Ronald Quimby - For: Roseburg Resources Co. - March 2002 - M 139-64 A & B

Found - County Surveyor's Office brass cap, properly marked.
Pine snag N.70°E, 70.0 ft. (Healed scar)

Pine snag (down) -NE

60" Fir S.24°W. 23.8 ft, (healed)

Fir stump N.75°W. 27.7 ft, (healed)

New BTs- 12" Tan Oak S.4°E, 15.2 ft. (Scribed T32S R8W S3 BT)

No other good trees in vicinity