

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8771)

A Fir tree, 5" dia., which I marked SC ¼ S on N. face for ¼ sec. cor., from which

A Chinquapin 6" dia., bears S.52°E., 52 lks. dist. mkd. SC ¼ S BT.

A Chinquapin 4" dia., bears N.65°W., 40 lks. dist. mkd. SC ¼ S BT.

BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8855)

The standard ¼ cor. of sec. 34, which is a Fir tree, 5" dia., mkd. and witnessed as described by the surveyor general. Alongside of tree, Set a diorite stone 18x12x10 ins., 14" in the ground, mkd. SC ¼ on N. face.

The bearing tree S. of line being dead, I obliterate markings on same and take new bearing tree as follows:

A Fir 8" dia., bears N.31°E., 18 lks. dist., mkd. SC ¼ S34 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-67

Found - No trace of corner stone nor NW. bearing tree.
5" Corner tree, now down, shows good scar.
8" now 12" D.Fir N.31°E., 11.9 ft., scribe visible "SC ¼ 34".

*Set brass cap at ¼ sec. cor. mkd:

COUNTY SURVEYORS OFFICE
DOUG CO
T32S R8W
¼ S 34
T33S
JOS CO
1968

New BT - 11" D.Fir N.70°W., 8.1 ft. mkd. SC ¼ S34 CS BT.
NE. bearing tree OK and tagged.

*Details of BC set added 5/24/2017 DCSO JC