

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Pages 8098-99)

Set a stone 18x14x10 ins., 10" in the ground mkd. with 2 notches on the E.; and 4 notches on the W. angles of same for the corner to secs. 2, 3, 34 and 35, from which

- A Fir 14" dia., bears N.82°E., 57 lks mkd. T31S R8W S35 BT
- A Fir 14" dia., bears S.65°E., 41 lks mkd. T32S R8W S2 BT.
- A Fir 16" dia., bears S.28°W., 30 lks mkd. T32S R8W S3 BT.
- A Fir 13" dia., bears N.35°W., 42 lks mkd. T31S R8W S34 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Jan. 1967 - C.S. file 54/36-73

Found - Pieces of stone at section corner.
14" now 27" D.Fir N.82°E., 34.2 ft. (Rec. 32.6') Old axe work, no scribe visible.
14" now 21" D.Fir S.65°E., 27.1 ft., shows good scar.
16" now 36" D.Fir S.28°W., 19.8 ft., bark scribe visible. T3 R8 S3 BT
13" now 30" D.Fir N.35°W., 27.1 ft., bark scribe visible. 31S 8

Set Brass cap at cor. mkd: County Surveyors Office

T	31	S	R	8	W
S	34		S	35	
S	3		S	2	
T 32 S					
1967					

Reblazed and rescribed:
27" D.Fir N.82°E., 34.2 ft. mkd. T31SR8W S35 CSBT
36" D.Fir S.28°W., 19.8 ft. mkd. T32S R8W S3 CSBT
30" D.Fir N.35°W., 27.1 ft. mkd. T31S R8W S34
Best way to reach corner is North on railroad to yellow tag on small Fir.

Fd. and Used in BLM Resurvey by James E. Jelley and James J. Carlson, Cadastral Surveyors, under Group #899, surveyed Aug. 1976/Nov. 1977 - (DCSO records Vol. 41 Page(s) 16185-86)

Ron Quimby - J. Leonard & N. Fromdahl Crew - 9/2013 - C.S. File 65/80-12

Condition report only
Found - 1967 DCSO brass cap
44" D.Fir S.28°W., 19.8
28" Fir S.65°E., 27.1 (now stump) (M83-26 S.62°E.)
continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35, T31-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

	36" Fir N.35°W., 27.7
	32" Fir N.82°E., 34.2
New -	Set alum post 2.0 East
	Re-tag all trees
Note -	No new trees due to burn July 2013