

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 1

Alias	Description

<p>Howard W. Johnstone - For: Roseburg Lumber Co. - April 1980 - M83-25</p> <p>-----</p> <p>Set - 5/8"x30" iron rod &amp; alum. cap. 16" cedar bears S.2°E., 22.8 ft. 7" cedar bears N.54°W., 31.0 ft.</p>
<p>Ron Quimby - Crew: J. Leonard &amp; N. Fromdahl - 10/2013 - C.S. File 65/80-39</p> <p>-----</p> <p>Found - 5/8" I.Rod with melted alum. cap alongside burnt root hole and burnt log with burnt BT tag N.54°W., 31.0 ft. Burnt hole with burnt log S.2°E., 22.8 ft.</p> <p>Set - alum. post 2.0 east &amp; 2.0 south.</p> <p>Note- Corner is near bottom of draw approx. 200' below road, badly burnt area 7/2013</p>
<p>BLM resurvey by Brandon G Courtright, Cadastral Surveyor, under Group No. 2754, surveyed May/July 2014 - (DCSO records, Vol. 58 page(s) 23375-6)</p> <p>-----</p> <p>The center ¼ sec. cor. of sec. 1, established by Johnstone, in 1980, and is accepted as the cor., monumented with an iron rod, 5/8" dia., firmly set, projecting 3" above ground, from which the remains of bearing trees mkd. by Johnstone</p> <p>A root hole bears S.2°E., 22.8 ft., alongside of which is a charred log, 13" dia., no marks visible.</p> <p>A butt of a charred log, 5" dia., bears N.58¼°W., 31.3 ft., no marks visible.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 32 S R 8 W C ¼ S 1 2014</p> <p>from which new accessories</p> <p>An iron rod, 5/8" dia., 36" long, driven 31" in the ground for a reference monument, bears S.29°46'11"W., 11.74 ft., with alum. cap mkd. RM T32S R8W C¼ S1 11.74 FT TO COR, and an arrow pointing to the cor.</p> <p>A Mag Nail, 2½ X ¼" dia., driven into a boulder, 2x3x3 ft., bears N.50°40'30"W., 16.30 ft.</p> <p>Deposit the iron rod inside the stainless steel post.</p>
<p style="text-align: right;">1</p>