

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 358700

PRIMARY CORNER DESCRIPTION Sec. cor. for 33 & 34 only, T31-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8170)

Set a Fir post 4" sq., 4 ft. long, 24" in the ground, for cor. to secs. 33 and 34, marked S33 R9W on NW.; S34 T31S on NE. face; with 3 notches on E. and W. edges, from which
A Fir 30" dia., bears N.8°E., 20 lks. dist. mkd. T31S R9W S34 BT.
A Fir 24" dia., bears N.20°W., 93 lks. dist. mkd. T31SR9W S33 BT.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12191)

Intersect at the cor. of secs. 33 and 34, which is a decayed post, mkd. and witnessed as described by the surveyor general. I perpetuate this cor., as follows: alongside the old cor.
Set an Iron post 3 ft. long, 2" dia., 24" in the ground, with brass cap mkd.

T31S	R9W
S 33	S 34
1917	

from which
A Fir 30" dia., bears N.8°E., 20 lks. dist. mkd. T31S R9W S34 BT. (Old BT)
A Fir 24" dia., bears N.20°W., 93 lks. dist. mkd. T31SR9W S33 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - March/April 1967 - C.S. File 54/32-56

Found - GLO 1917 brass cap at corner. Cap badly bent and loose. Reset brass cap and try to straighten.
30" now 28" D.Fir N.8°E., 13.2 ft., shows good face.
24" now 28" D.Fir N.20°W., 61.4 ft., shows good face
New BT - Reblazed and rescribed: 28" D.Fir N.8°E., 13.2 ft. scribed "T31SR9W S34 CS BT"

Tony Hostetter - For: Plum Creek Co. - Jan. 22, 2009 - C.S. File 65/66-14

Found - 35" fir, face evident, BLM tag, orig. BT marked by Byars in 1900 & remarked by Powell in 1967, the monument & the other BT are gone.

continued next page

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 358700

PRIMARY CORNER DESCRIPTION Sec. cor. for 33 & 34 only, T31-9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Set - 5/8"x36" rebar with plastic cap, marked "HOSTETTER LS 1975" at rec. bearing & distance from the 35" Fir BT.

New BTs- 7" fir, scribed "S34 SW BT", BT tag, bears S.18°E., 4.0 ft. to 20D spike placed in root collar below scribing.

9" fir, scribed "S33 SE BT", BT tag, bears S.28°W., 14.0 ft. to 20D spike placed in root collar below scribing.

7" fir, scribed "S33 SW BT", BT tag, bears S.77°W., 15.0 ft. to 20D spike placed in root collar below scribing.