

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36 only, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12198)

-----  
Set an iron post 3 ft. long, 2" dia., 24" in the ground, for standard cor. of secs. 35 and 36, with brass cap mkd.

S C  
T32S | R9W  
S 35 | S 36  
-----  
1917

from which

A Fir 36" dia., bears N.14°E., 12 lks. dist. mkd. SC T32S R9W S36 BT.

A Fir 26" dia., bears N.7°W., 61 lks. dist. mkd. SC T32S R9W S35 BT.

Daren Cone - For: Oregon Department of Forestry - 10/2015 - M170-22

-----  
Found - 2" OD GIP with 2½" BC per 1917 GLO resurvey protrudes 14" out of ground.

BTs per 1917 GLO resurvey -

36" dia. fir bears N.14°E., 7.9', now 32.7" DBH, scribe healed over, DCSO YMLP (assume diameter was incorrectly recorded in 1917 resurvey as bearing, distance and scribe wound matches)

26" dia., fir bears N.7°W., 40.3' now 27" DBH, scribe healed over a creek 2' wide, course south east bears north 31' and south 12'.

New - ½" x 5' white fiberglass rod bears north 1'.

Note - Set 5' metal "T" fence post set on line 19.1 ft south of ridge top road centerline, course N.70°E., and 2031.05' north of standard corner scribed "PLS 43362" in flange.