

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 619700

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 36, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8168)

Marked a Fir 10" dia., on rocky point S.36 ¼ S on N. face for the ¼ sec. cor. No other trees within limits for witness trees. Pits impracticable.

GLO resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12187)

The ¼ cor. of sec. 36, T31S R9W, which is a Fir tree, marked as described by the surveyor general. I mark bearing trees for this corner, as follows:

A Laurel 7" dia., bears N.55½°E., 123 lks. dist. mkd. ¼ S36 BT.

A Maple 14" dia., bears N.8°W., 57 lks. dist. mkd. ¼ S36 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - March/April 1967 - C.S. File 54/32-61

Found - 10" D.Fir Corner Tree, now 16", shows good scar on North face.

14" Maple now 17", N.8°W., 37.6 ft., shows scar.

7" Laurel now 7", N.55½°E., 80.2 ft. (Rec. 83.2 ft.), rotten scribing visible "¼ S".

New BT - 7" Laurel N.54½°E., 81.8 ft. mkd. ¼ S36 CS BT.

Corner lies in very rocky area on North slope approx. 110 ft. East of creek.