

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 36 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8838)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for cor. of sec. 36 only, with brass cap mkd.

1/4
S36
1917

from which

A Fir 20" dia., bears S.72°W., 67 lks. dist. mkd. 1/4 S36 BT.

A Fir 8" dia., bears N.35°W., 33 lks. dist. mkd. 1/4 S36 BT

Survey by Robert M. Thompson - Wit: R. Gledhill - Feb. 28, 1961 - C.S. File 51/181-2

I find 3/4" I.P. with brass cap, from which a
20" D.Fir bears S.72°W., 67 lks.(OBT) now 30" cut stump.
8" D.Fir bears N.35°W., 33 lks.(OBT) now 12" and down.

To renew, I scribe a

6" D.Fir S.67°W., 28.4 ft. "1/4 S36 BT"

6" D.Fir, North 9.6 ft.

No other trees within reasonable distance.

Douglas Co. Surveyors Office - John M. Powell, and crew - June 1967 - C.S. File 54/44-32

Found - Orig. 20" D.Fir, now stump, S.72°W., 44.2 ft., scribe visible.

Orig. 8" D.Fir, now down, N.35°W., 21.8 ft.

GL0 brass cap at 1/4 cor., properly mkd. in 1917.

6" D.Fir, now dead, S.67°W., 28.4 ft. scribe visible.

6" D.Fir, now dead, North 9.6 ft. scribe visible.

Not having any bearing trees to mark, I tie this corner to the 1/4 corner to sec. 31, T32S R8W, which is South 29.0 ft.

All original trees tagged.

Corner lies 145.0 ft. S. of spur. Location tag approx. 495 ft. North of corner on Dutch Henry Trail Road.