

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8941)

A Yew, 5" dia., which I marked $\frac{1}{4}$ S on N. face, for $\frac{1}{4}$ sec. cor., from which

A W.Fir 6" dia., bears S.45°E., 24 lks. dist., marked $\frac{1}{4}$ S BT.

A W.Fir 8" dia., bears N.79°W., 18 lks. dist., marked $\frac{1}{4}$ S BT.

BLM remonumentation by James E. Jelley, Cadastral Surveyor, under Group #350, surveyed Nov. 1968/June 1969 - (DCSO records Vol. 33 Page(s) 13929B)

The $\frac{1}{4}$ sec. cor. of secs. 7 and 18, determined at the center of the root hole of the original corner tree, alongside of which is lying the corner tree, a Yew, 5" dia., mkd. $\frac{1}{4}$ S on partially healed blaze, from which the remaining original bearing tree:

A W.Fir 18" dia., bears S.45°E., 14 lks. dist., with healed blaze. (Rec. 24 lks.)

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 33 S R 4 W

$\frac{1}{4}$ $\frac{S 7}{S 18}$

1968

from which a new bearing tree

A W.Fir 7" dia., bears N.27 $\frac{1}{2}$ °W., 35 lks. dist., mkd. $\frac{1}{4}$ S7 BT.

Douglas Co. Surveyors Office, John Powell, W.Penley and Jack Heritage, crew - June 5, 1970 - C.S. File 54/114-6

Found - 5" Yew corner tree, now down and rotted, scribe visible " $\frac{1}{4}$ S".

Orig. 6" now 17" W.Fir S.45°E., 10.0 ft. (Rec. 15.8 ft.) shows good scar.

8" W.Fir N.22 $\frac{1}{2}$ °W., 23.1 ft. scribed $\frac{1}{4}$ S7 BT.

1968 BLM brass cap at $\frac{1}{4}$ cor., properly marked.

Reblazed and rescribed:

17" W.Fir S.45°E., 10.0 ft. mkd. " $\frac{1}{4}$ S18 CS BT".