

PRIMARY CORNER DESCRIPTION A.P. #1, N. bdy. Sec. 3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by McKenzie and Eckelson, Deputy Surveyors, under Contract #328, dated June 17, 1879 (DCSO records Vol. 20 Page(s) 8465)

Set post for ¼ sec. corner, from which
A Fir 8" dia., bears N.45°W., 14 lks. dist.
A Chinquapin 7" dia., bears S.30°W., 37 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8480)

The standard 1/4 sec. corner, post destroyed; bearing trees standing, from which I reestablish this ¼ corner as follows:
Set a basalt stone 12 x 8 x 8 ins., 8" in the ground, for standard ¼ sec. corner, marked S.C. ¼ on N. face, from which
A Fir 8" dia., bears N.45°W., 14 lks. dist., marked S. C. ¼ S BT.
A Chinquapin 7" dia., bears S.30°W., 37 lks. dist., marked S.C. ¼ S BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16529-30)

The former standard ¼ sec. cor. of sec. 34, changed to an angle point by Chapman and Nicklin, monumented with a basalt stone, 12 x 8 x 8 ins., firmly set 6" in the ground, mkd. SC ¼ on N. face, from which the remains of an original bearing tree:

A root hole bears N.45°W., 14 lks. dist.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap marked
AP 1
T 32 S R 4 W
S 34
1975

from which new bearing trees:
A Fir 9" dia., bears N.12½°E., 157 lks. dist., mkd. AP1 S34 BT.
A Cedar 7" dia., bears N.30 3/4°W., 9 lks. dist., mkd. AP1 S34 BT.
Deposit corner stone alongside iron post.
Corner is located at top of cut bank of road, edge bears NW. and SW., and on a spur, slopes E.