

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION C C for Secs. 1 and 2 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - GLO survey by Edward F. Sharp, Deputy Surveyor under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8958)

I proceed to set closing cor. at point of intersection by setting a post 4 ft. long, 4" sq., 24" in the ground for closing corner to secs. 1 and 2 marked C C T33S R5W on S.; S1 on E.; and S2 on W. faces with 1 notch on E. and 5 notches on W. faces, from which
A W.Fir 12" dia., bears S.44°E., 41 lks. dist. marked T33S R5W S1 BT.
A Y.Pine 36" dia., bears S.26°30'W., 80 lks. dist., marked T33S R5W S2 BT.
A W.Fir 12" dia., bears N.85°E., 54 lks. dist. marked T33S R5W C C S1 and 2 BT.

Ben B. Irving - June 1930 - C.S. File 46/109

Location identified from O.B.T.s as described in government field notes.
12" Fir S.44°E., 41 lks.
12" Fir N.85°E., 54 lks.
Pine S.30°W., cut for wood but scribe marks visible on stump.
Blazed and scribed for new BT:
12" Fir S.32°W., 46 lks. "T33S R5W S2 CS BT".
C.O. Garrett had driven a 1½" I.P. for corner.
All O.B.T.s reblazed and scribed.

BLM resurvey by Joseph Gawron, John Jelley, Rollin Aanrud, Cadastral surveyors, under Group #'s 350 and 566, surveyed, March 1965/Dec. 1967 (DCSO records Vol. 34 Page(s) 13975)

The closing cor. of secs. 1 and 2, monumented with an iron pipe 1½" dia., firmly set, flush with the ground surface, from which the remaining original bearing trees mkd. by Sharp
A D.Fir 22" dia., bears N.85°E., 54 lks. dist., mkd. T33S R5W CC on opened blaze.
A sawed W.Fir stump 16" dia., bears S.34°E., 41 lks. dist., no marks visible. (Record bearing S.44°E.)
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 26 ins. in the ground, directly over the iron pipe, with brass cap marked

(Cont. Next Page)

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION CC for Secs. 1 and 2 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T 32 S
S 35

S 2 | S 1
T 33 S R 5 W
C C
1965

from which

A D. Fir 12" dia., bears S.14°E., 31½ lks. dist., mkd. T33S
R5W S1 CC BT.

No suitable accessory available in the SW. quadrant.

Cor. Fd. and Used in BLM survey by Lynn Roseberry, under
Group #723, Surveyed, Nov/Dec. 1970 (DCS0 records, Vol. 36
Page 14830)

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy -
S.J. Flause, crew - Jan. 15, 1985 - C.S. File 62/25-9

Found - Iron post and brass cap monument from 1965 BLM
resurvey, firmly set and protruding 8" above
ground. (Orig. post and 1½" I.P. per Irving, not
found. 1965 BLM resurvey set monument over pipe)
Orig. 12" Fir now a 36" dia. stump with visible
scribing "33S R5W CC" in opened blaze bears
N.85°E., 35.6 ft.

Possible orig. BT called by 1965 resurvey, an 18"
decayed Fir stump with chop and saw evidence to
the center, no scribing or blaze visible. BLM
resurvey calls bearing S.34°E., 41 lks., falls at
West edge of gravel road. Orig. bearing and
distance S.44°E., 41 lks. falls in traveled
roadway. We measure S.35½°E., 26.9 ft.

No other original BTs found.

From Irving visit, not called in BLM resurvey, a 12"
Fir now 34" dia., with pitched over single blaze
bears S.32°W., 30.4 ft. Tree is at random fence
corner, top has been cut out at about 30 ft.
high. (healthy and growing)

From 1965 BLM resurvey, a 12" Fir now 21" dia. with
well healed single blaze bears S.14°E., 20.8 ft.

New Accessories:

Set bridge spike (½" x 8") marked B0 1 in pitch ring
of a 36" dia., 18" tall Pine stump. Spike set
through 2" dia. washer marked "DCS0". Spike bears
N.34°W., 50.9 ft.

(Cont. Next Page)

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION C C for Secs. 1 and 2 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set 5/8" x 30" iron rod with alum. cap marked "Douglas Co. Surveyor B0 2" in the ground at the base of a 36" dia. Madrone tree. I.R. bears N.86°E., 89.4 ft. Madrone tree referred to is triple trunk with dia. measure at base. Monument is 10 ft. West of West edge of a 10 ft. wide gravel road course S.20°E. and N.20°W. 12 ft. North of a random easterly-westerly fence line.

Fd. OK, by D. Bentz, August 1993, Land partition #1993-0078
Fd. Ok by Ron Quimby, 11/2006 - 2006-0105A&B

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCS0 records Vol. 59 Page(s) 24109-10)

The closing cor. of secs. 1 and 2, perpetuated by Irving, Douglas Co Deputy Surveyor, in 1930; subsequently reported by Roseberry in 1970; and perpetuated by the Douglas County Surveyor's Office in 1985; monumented with an iron post, 2½" dia., firmly set, projecting 6" above the ground, with brass cap (properly) mkd.
from which a BT mkd. by Irving, not reported by Roseberry
A fir, 42" dia., bears S.35°W., 29.8 ft., with a healed blaze.
and the remains of bearing trees reported by Roseberry
A rotted fir stump, size indeterminate, bears N.85°E., 35.6 ft., no marks visible. (Original)
A fir, 28" dia., bears S.14°E., 20.8 ft., with a healed blaze.
and accessories established by the Douglas County Surveyor's Office
An iron rod, 5/8" dia., firmly set, projecting 2" above the ground, N.85°35'37"E., 89.59 ft., with an aluminum cap mkd. DOUGLAS CO. SURVEYOR B02.
A rotted ponderosa pine stump, size indeterminate, bears N.34°W., 51.8 ft., no marks visible. The bridge spike set in the stump by the Douglas County Surveyor's Office was not recovered.