

PRIMARY CORNER DESCRIPTION Sec Cor for 5, 6, 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 431 survey dated March 29 1882 (DCSO records Vol. 21 Page(s) 9021)

Set a Fir post, 4 ft. long, 4" sq., 20" in the ground, marked T33S R6W S5 on NE. face; S8 on SE. face; S7 on SW. face; and S6 on NW. face, also 5 notches on S. and E. angles of same, from which

- A Vine Maple 4" dia., bears N.80°E., 18 lks. dist. mkd. T33S R6W S5 BT.
- A Chinquapin 8" dia., bears S.60°E., 18 lks. dist. mkd. T33S R6W S8 BT.
- A Laurel 14" dia., bears S.10°W., 10 lks. dist. mkd. T33S R6W S7 BT.
- An Alder 14" dia., bears N.15°W., 100 lks. dist. mkd. T33S R6W S6 BT.

Douglas Co. Surveyors Office - James W. Byron and crew - Feb. 14, 1963 - C.S. File 53/8-1

Found - Rotted stump section of orig. 14" Laurel, S.10°W., 6.6 ft. shows reverse scribe marks.
No other original bearing trees found.
Call North to creek checks OK.
Find new 2" x 2" stake and mound of rocks at corner.

Set Brass cap at cor. mkd: County Surveyors Office
T 33 S R 6 W
S 6 | S 5
S 7 | S 8
1963

New BTs -8" Laurel bears S.20°W., 7.5 ft. scribed S7 T33S R6W CS BT.
8" Laurel bears S.10°E., 8.2 ft. scribed S8 T33S R6W CS BT.
9" R.Fir bears S.80°E., 76.9 ft. scribed S8 T33S R6W CS BT.
No trees near to NE or NW.

Cor. Fd. and used in BLM survey by J. Gawron, Group #'s 350 and 626, 1963/64 (DCSO records, Vol. 33 Pages 13844-45)

Cor. Fd. OK, by R. Thompson, April 1984, RM 3-61
Cor. Fd. OK, by G. Nygren, March 1994, M 118-79