

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec Cor for 3, 4, 9 and 10

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Wells Lake and Geo. W. Hyde, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 21 Page(s) 9008)

-----  
Set post cor. to secs. 3, 4, 9 and 10, from which  
A Fir 12" dia., bears S.52°W., 46 lks.  
A W.Oak 10" dia., bears N.45°W., 8 lks.  
A W.Oak 7" dia., bears N.8°E., 9 lks.  
A W.Oak 9" dia., bears S.62°E., 79 lks.

Survey by Richard L. Templin Jr., RE 3024 - Oct. 1954 - C.S. File 41/310

-----  
Found - An old pitch fence corner post common to the intersection of four fences.  
Rotted stump of orig. 12" Fir BT, with chopped face and trace of scribing under five inches of rotted wood, said stump bearing S.52°W., 46 lks. dist. Other BTs completely gone. (Lake & Hyde, 1855)  
Set 1½" Iron pipe with galv. cap and alum. tag mkd. "RE3024" on the North side of pitch corner post.  
New BTs -14" Fir bears S.55°W., 35.0 ft. mkd. T33S R6W S9 BT  
14" Madrone bears N.82°W., 46.3 ft. mkd. T33S R6W S4 BT.  
10" Yellow Pine bears S.17°W., 44.2 ft. mkd. T33S R6W S9 BT.  
Set BLM bearing tree tags on Madrone and Yellow Pine BTs.

Fd. OK, DCSO, Oct. 1967, C.S. File 54/53-16

Gerald Nygren - 11/23/94 - M 121 - 31

-----  
Found - BLM Brass Cap  
(1954 B.T.) 28" D.Fir, S.57°30'W., 35', healed blaze  
(BLM BT) 12" D.Fir, N.64°15'W., 19.5', vis. scribe.  
(BLM BT) 18" D.Fir, S.61°30'E., 75.5', vis. scribe.  
(BLM BT) 8" Madrone, N.52°30"E., 73.5', vis. scribe.

Fd. Ok by K. DeGroot, March 1996, M 123-52

continued next page

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Cor Secs 3, 4, 9, & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #1736, surveyed June/Sept. 1994 - (DCSO records Vol. 52 Page(s) 19728-9)

-----  
The cor. of secs. 3, 4, 9, & 10, perpetuated by Richard L. Templin Jr., in 1954, from original evidence no longer in existence; monumented with an iron pipe, 1½ ins. diam., firmly set, projecting 4 ins. above the ground, with an aluminum tag wired to it mkd. RE3024, from which the remains of bearing trees mkd. by Templin:

A rotten pine stump, size indeterminate, bears S.17°W., 66 lks., no marks visible.

A fir, 26" diam., bears S.57½°W., 52½ lks., with healed blaze.

A madrone stump, 18" diam., bears N.82½°W., 69½ lks., with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, directly over the iron pipe, with brass cap mkd.

T33S	R6W
S 4	S 3
S 9	S 10
1994	

from which new bearing trees

A madrone, 8" diam. bears N.52½°E. 73½ lks. mkd. T33S R6W S3 BT

A fir, 18" diam., bears S.61½°E., 75½ lks. mkd. T33S S6W S10 BT

A fir, 13" diam., bears N.64¼°W., 19½ lks., mkd. T33S R6W S4 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is located at the cor. of woven wire fences, bears N, E, & S.

Fd. BC by R.Wytcherly 5/2008 - M156-4  
 Fd. Ok by R. Wytcherley - 10/2010 - M161-44  
 Fd. as per 1994 renewal - by D Edwards, 2/2016 - M170-55A&B  
 Fd. as per record. by P Drossos 1/2024 M183-37