

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wells Lake and Geo. W. Hyde, Deputy Surveyors,  
under Contract #54, dated Feb. 19, 1855 (DCSO records Vol.  
21 Page(s) 9009)

-----  
Set qr. sec. post, from which  
A W.Oak 11" dia., bears N.79°E., 130 lks.  
An Ash 10" dia., bears S.59°W., 380 lks.

W. Briggs - For: H.Elliff - 11/20/1873 - Field 97 Book Pg 30

-----  
Set qr. sec. post, from which  
W.Oak 11" dia., N.79°E., 130 lks.  
Ash 10" dia., S.59°W., 380 lks.

Survey by Ronald A. Brandt - For: Robert Dollar Co. - Jan/May  
1973 - C.S. File 55/294 and M 49-21

-----  
(In corner of Tunnel Road)  
Set 12" x ½" sq. shank bridge spike, 1 1/16" round head,  
flush in asphalt surface, from which bears  
1" x 36" I.Rod 4" high at SE side of 19.4" P.Pine,  
N.33°59'W., 34.5 ft. and  
10" W.Oak N.62°20'E., 29.75 ft. mkd. ¼ PS841 BT.

Gerald Nygren - 11/23/94 - M 121 -31

-----  
Found - (Brandt ref.) 1" I.R., N.33°54'52"W., 34.5'.  
(Brandt B.T.) 18" W. oak, N.62°24'E., 29.75',  
healed blaze  
Set - concrete nail in pavement using following refs.  
New BTs -18" alder, N.3°W., 26.6', scribed "¼ S4 BT".  
26" alder, S.59°W., 44.8', not scribed

Kris DeGroot - For: Joseph & Catherine Poorhammer - April  
1996 - M 123-52

-----  
Found - ½" Square shank bridge spike.

Fd. ½" Sq. bridge spike by R.Wytcherly 5/2008 - M156-4

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda  
- 6/19/2008 - C.S. File 67/25-57

-----  
Found - 1"+ dia., spike head, firmly set 5" below asphalt  
surface of Tunnel Rd. (from 1973 ren) Corner lies  
8 ft. Northeasterly from centerline of Tunnel Rd.  
No evidence of orig. BTs found.  
continued next page

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From 1973 renewal 1 BT & 1 BO:

10" now 27" DBH W.Oak with a fully healed double blaze bears N.62½°E., 29.8 ft. as per rec.

1" dia., iron rod, firmly set with top approx. 1" below ground & at SE edge of a large Ponderosa Pine, bears N.34°W., 34.5 ft. (as per rec.)

From 1994 renewal, 2 then new BTs (Erroneously identified as Alders) now fd. Ash BTs:

26" Alder now a double trunk Oregon Ash, the larger NE trunk of which is 28" DBH & the CRC of which bears S.59°W., 44.8 ft. (as per rec.)

18" Alder now 18" dia., 2 ft. tall Oregon Ash stump with no clear blaze evidence, bears N.7°W., 26.6 ft. (rec. N.3°W., 26.6')

New BT tags with correct bearing & dist. are placed on both Oregon Ash BTs.

Relationship to paved rd & nearest residence driveway shown in sketch (See sketch in file.)

Note - Monument is under pavement in north bound lane & at a sharp curve of Tunnel Rd. (Co. Rd. 98A) Just east and south from Glendale.

Compass decl. 16¼°E.

Fd. Ok by R. Wytcherley - 10/2010 - M161-44

Fd. as per 2008 renewal - by D Edwards, 2/2016 - M170-55A&B