

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias	Description

GLO survey by Wells Lake and Geo. W. Hyde, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 21 Page(s) 9006)

-----  
Set qr. sec. post on North slope, from which  
A Fir 5" dia., bears S.64°E., 54 lks.  
A Fir 16" dia., bears N.46°W., 28 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Oct. 1967 - C.S. File 54/53-34

-----  
Found - Unrecorded 1/2" Iron rod at 1/4 corner and found to be at correct bearing and distance.  
5" now 9" D.Fir S.64°E., 34.6 ft., shows scribing "1/4 S2 BT"  
16" now 30" D.Fir N.46°W., 18.5 ft., shows scribing of "S".  
New BT - 26" D.Fir S.10°E., 14.7 ft. mkd. 1/4 S2 CS BT.  
This corner lies in the SW corner of old cutting unit.

Fd. OK, J Hollingsworth, July 13, 1988, C.S. 63/62 & M 107-16

Fd. OK, June 1990, M 110-30  
Fd. OK by Nygren, June 1998 - M130-10

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records Vol. 59 Page(s) 23781-2)

-----  
The 1/4 sec. cor. of secs. 2 and 3, perpetuated by person(s) unknown, further perpetuated by the Douglas County Surveyor's Office in 1967; monumented with an iron rod, 1/2 in. dia., firmly set, projecting 16" above the ground, from which original bearing trees  
A fir, 24" dia., bears S.64°E., 32.3 ft., with a healed blaze. (Record, 35.6 ft.)  
A fir, 40" dia., bears N.46°W., 18.5 ft., with no marks visible on partially open blaze.  
and a BT mkd. by the Douglas County Surveyor's Office  
A fir, 38" dia., bears S.11 3/4°E., 15.2 ft., with a healed double blaze.  
At the corner point  
Set a stainless steel post, 28" long, 2 1/2" dia., 25" in the ground, directly over the iron rod, with brass cap mkd.  
T33S R6W  
1/4  
S 3 | S 2  
2018