

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page 8551)

Set post cor. of Tps. 32 and 33 S. Rs. 5 and 6 W. on N. slope of hill, from which

- A Laurel 10" dia., bears N.88°W., 30 lks.
- A Laurel 5" dia., bears N.38°E., 30 lks.
- A Laurel 10" dia., bears S.38°E., 54 lks.
- A Fir 24" dia., bears S.37°W., 69 lks.

County Surveyors Office - James Byron, Deputy, John Powell, crew - March 19, 1968 - C.S. File 49/112

Found - 1½" iron pipe at section corner, unrecorded, but noted on M 12-51.

Orig. 10" Laurel, now rotten, S.38°E., 35.6 ft. scribe found, "W 3" on chip.

10" Laurel, now hole, N.88°W., 19.8 ft.

5" Laurel, now hole, N.38°E., 19.8 ft.

No trace of SW BT.

New BTs -11" D.Fir S.65°W., 27.1 ft. mkd. T33S R6W S1 CS BT

8" D.Fir S.84°E., 15.3 ft. mkd. T33S R5W S6 CS BT.

This corner lies 200 ft. (Rec. 198 ft.) E of S36|S31 T32-R6-5W

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #1474 survey Feb. 1989/June 1992 - (DCSO records Vol. 53 Pg(s) 20357)

The standard cor. of T33S, R5 & R6, perpetuated & recorded by the Douglas Co. Surveyor's Office in 1958, monumented with an iron pipe, 1½" dia., firmly set, projecting 4" above the ground, from which the remains of an OBT:

A decayed Madrone, size indeterminate, bears S.38°E., 54 lks. no marks visible.

and BTs mkd. by DCSO

A Fir, 14" dia., S.84°E., 23½ lks., w/healed double blaze.

A Fir, 20" dia., S.65°W., 40½ lks., w/healed double blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T32S R5W
 S31
 S 6|S 1
 R 6 W|R 5 W
 T33S
 1989

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Fd. Ok by K DeGroot, 7/2006 - M151-7