

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9037)

Set a Fir post, 4 ft. long, 4" sq., 2 ft. in the ground, mkd. T33S R7W S2 on NE.; S11 on SE.; S10 on SW.; and S3 on NW.; faces, also 5 notches on S. and 2 notches on E. angles of same for corner to secs. 2, 3, 10 and 11, from which

 A Maple 7" dia., bears N.32°E., 92 lks. dist., mkd. T33S R7W S2 BT.

 A Fir 26" dia., bears S.58°E., 28 lks. dist., mkd. T33S R7W S11 BT.

 A Sugar Pine 6" dia., bears S.42°W., 18 lks. dist., mkd. T33S R7W S10 BT.

 A Cedar 16" dia., bears N.70°W., 8 lks. dist., mkd. T33S R7W S3 BT.

J. W. Cole, Surveyor - Wit: E.H. Bahnert - Dec. 1, 1923 - Field Book 52 Page 4

Found - Remains of old stake & 3 OBTs which check with Govt. field notes: The Sugar Pine was entirely gone, and I marked:

 A Maple 10" dia., S.45°45'W., 25.0 ft.

Set a Creek boulder 8 x 12 x 15 marked on top + C.S. with 2 notches on E. and 5 notches on South sides.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W.Penley, crew - March 12, 1968 - C.S. File 54/36-166

Found - Orig. 7" Maple, now stob, N.34°E., 60.7 ft. (rec. N.32°E.)

 Orig. 26" D.Fir, now stump, S.58°E., 18.5 ft. bark scribe visible, T33

 Orig. 16" now 22" Cedar N.70°W., 5.3 ft., tree partly opened, no scribe visible.

 No trace of 10" Maple or corner stone.

Set Brass cap at cor. mkd: County Surveyors Office

T	33	S	R	7	W
		S	3	S	2
		S	10	S	11
					1968

New BTs -30" D.Fir N.2°E., 88.6 ft. mkd. T33S R7W S2 CS BT.

 42" D.Fir, East, 11.6 ft. mkd. T33S R7W S11 CS BT.

Reblaze and rescribe:

 22" Cedar N.70°W., 5.3 ft. mkd. T33S R7W S3 CS BT.

Note - This corner lies East of Creek approx. 25.0'

Cont.

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. Fd. and used in BLM survey by Aanrud and Roseberry, under Group #845, surveyed April/Nov. 1975 (DCSO records, Vol. 41 Pages 16270-71)

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #1050, surveyed May/Sept. 1981 (DCSO records Vol. 45 Page(s) 17414)

The Sec. cor. perpetuated and recorded by the DCSO in 1968, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground with 1968 brass cap

from which the remains of the original bearing trees:

A sawed Maple stump 15" dia., bears N.33°E., 87 lks. dist., with healed blaze. (Rec. N.32°E., 92 lks.)

A sawed Fir stump 32" dia., bears S.63 3/4°E., 29 1/2 lks. dist., with illegible scribe marks visible on open burned blaze. (Rec. S.58°E., 28 lks.)

A Cedar 25" dia., bears N.70°W., 8 lks. dist., no marks visible on decayed blaze. This tree rescribed the County with scribe marks T33S R7W S3 CS BT visible on partly healed blaze.

and bearing trees mkd. by the County Surveyors Office

A Fir 36" dia., bears N.3°E., 134 lks. dist., with healed blaze.

A sawed Fir stump 40" dia., bears S.89 1/2°E., 20 lks. dist., with scribe marks T33 visible on partly healed blaze.

and new bearing trees:

A Fir 4" dia., bears S.35 1/2°E., 22 lks. dist., mkd. T33S R7W S11 BT.

An Alder 10" dia., bears S.58 1/2°W., 24 lks. dist., mkd. T33S R7W S10 BT.

FD. OK by Lloyd Smith, 3/85, M 98-47

Gerald Nygren - For: Plum Creek Timberlands, LP - March 2014 - M167-56

Fd Douglas Co. Surveyors Brass cap & BTs as shown on M98-47.