

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

NOT IN DOUGLAS COUNTY

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #420, dated Sept. 16, 1881 (DCSO records Vol. 21 Page(s) 9027)

At the corner, a Fir tree, 32" in dia., which I marked T33S R7W S13 on NE., S24 on SE., S23 on SW., & S14 on NW., faces; also 3 notches on S. and 1 notch on E. edges for the cor. to secs. 13, 14, 23, & 24, from which:

- A S.Pine, 14" dia., bears N.50°E., 111 lks., mkd. T33S R7W S13 BT.
- A S.Pine, 26" dia., bears S.40°W., 39 lks., mkd. T33S R7W S24 BT.
- A Fir, 14" dia., bears S.55°W., 34 lks., mkd. T33S R7W S23 BT.
- A Fir, 16" dia., bears N.36°W., 48 lks., mkd. T33S R7W S14 BT.

BLM resurvey by John Jelley, Rollin D. Aanrud, and Lynn Roseberry, Cadastral Surveyors, Under Group #'s 350 & 688, surveyed May 1969/March 1970 (DCSO records Vol. 35 Page(s) 14475)

The cor. of secs. 13, 14, 23, & 24, occupied by the original corner tree, a fir, 42" dia., with illegible scribe marks visible on bark blazes on NE & SE faces, from which the original BTs:

- A pine, 30" dia., bears N.55½°E., 98 lks., with healed blaze. (Record N.50°E., 111 lks.)
 - A stump hole, bears S.40°E., 39 lks.
 - A decayed fir stump, 14" dia., bears S.37°W., 32 lks., with no marks remaining. (Record, S.55°W., 34 lks.)
 - A sawed fir stump, 21" dia., bears N.34°W., 50 lks., with healed blaze. (Record, N.36°W., 48 lks.)
- and bearing trees mkd. by Richard L. Templin, Jr. R.E. #3024, in 1955
- A fir, 22" dia., bears S.15°E., 68 lks., w/healed blaze.
 - A fir, 26" dia., bears N.20°W., 106 lks., w/healed blaze.
- and a new bearing tree and reference monument
- A fir, 18" dia. bears S.86°W. 38 lks. mkd T33S R7W S23 BT.
 - An iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, bears N.45°W., 19½ lks., with brass cap mkd: T33S R7W S14 RM 19½ lks. 1969 and an arrow pointing to the corner.