

-17-

Subdivisions of T 21 S., R 8 W.,

CHAINS

79.90 The cor. to secs. 22, 23, 26 & 27

Land rough, mountain side, in places very steep.

Soil very thin and poor

Timber mostly fir poor quality.

Thick undergrowth of Sallal--79.90 chs.

North between section 22 & 23

Va. 20*25' E.

On Mountain Top

40.00 Set post 4 ins. diam., 4 ft. long with marked stone 12 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W face from which:

Alder, 5 ins. diam., bears E. 15 lks. dist.,

Marked $\frac{1}{4}$ S B T

Alder 4 ins. diam., bears S.45*W., 25 lks. dist.,

Marked $\frac{1}{4}$ S B T

80.00 Set post 6 ins. diam., 4 ft. long with marked stone 12 ins. in ground for cor. to secs. 14, 15, 22 & 23, marked T 21 S S 14 on NE, R 8 W, S 23 on SE, S 22 on SW, S 15 on NW face with 3 notches on S and 2 on E.

Edge from which:

Alder, 5 ins. diam., bears N.16*E., 19 lks. dist.,

Marked T 21 S R 8 W S 14 B T

Alder, 3 ins. diam., bears S.22*E., 35 lks. dist.,

Marked T 21 S R 8 W S 22 B T

Alder, 7 ins. diam., bears S.15*W., 42 lks. dist.,

Marked T 21 S R 8 W S 22 B T

Alder, 4 ins. diam. bears N.33*W., 71 lks. dist.,

Marked T 21 S R 8 W S 15 B T

Land on Mountain nearly level

Soil thin, full of rocks

Timber, Fir and Alder

Thick undergrowth of Sallal--80 chs.

September 14, 1883