

Subdivisions of T. 21 S., R. 8 W.,

CHAINS

80.05 The cor. to secs. 15, 16, 21 & 22
 Land on Mountain level
 Soil, poor and thin
 Timber, Fir and Cedar
 Thick undergrowth of Sallal and Thimbleberry--80.05 chs.

North, between secs. 15 & 16

Va. 20* E.

Along East slope

40.00 Set post 4 ins. diam., 4 ft. long, 12 ins. in ground with
 marked stone for $\frac{1}{4}$ sec. cor., Marked $\frac{1}{4}$ S on W face from
 which:

Hemlock, 5 ins. diam., bears S.80*E., 6 lks. dist.,

Marked $\frac{1}{4}$ S B T

Hemlock, 5 ins. diam., bears N.50*W., 9 lks. dist.,

Marked $\frac{1}{4}$ S B T

55.00 Cross Creek 10 lks. wide flows NW

77.00 Branch 3 lks. wide flows W

80.00 Set post 6 ins. diam., 4 ft. long with marked stone 12
 ins. in ground for cor. to secs. 9, 10, 15 & 16, marked
 T 21 S, S 10 on NE, R 8 W, S 15 on SE, S 16 on SW, S 9
 on NW face with 4 notches on S and 3 on E edge from
 which:

Maple, 6 ins. diam., bears N.45*E., 36 lks. dist.,

Marked T 21 S R 8 W S 10 B T

Maple, 8 ins. diam., bears S.50*E., 48 lks. dist.,

Marked T 21 S R 8 W S 15 B T

Maple, 12 ins. diam., bears S.70*W., 27 lks. dist.,

Marked T 21 S R 8 W S 16 B T

Fir, 70 ins. diam., bears N.45*W., 20 lks. dist.,

Marked T 21 S R 8 W S 9 B T

Land very rough and steep

Soil, thin and poor

Timber, scrubby Fir

Thick undergrowth of Sallal--80 chs.