

Subdivisions of T. 21 S., R. 9 W.

CHAINS	<p>Thence I run South on blank line</p> <p style="text-align: right;">Va. 20*E.</p>	
43.26	chs. to a point 168 lks. E. of $\frac{1}{4}$ Sec. Cor. continued South from $\frac{1}{4}$ Sec. Cor. and at	
83.79	to a point 27 lks. E. of Cor. to Secs. 25, 30, 31 and	
	and 52.36	
	The error in Lat. is therefore 3.79 chs. and the error of departure is 195 lks. E.	
	I find also that there had been established a Corner near where I intersected the E. Bdry of Tp. but had been destroyed.	
	I, therefore, run a true line bet. Secs. 24 and 25, setting a closing corner.	
	Commencing again at Cor. to Secs. 23, 24, 25 and 26, I run thence	
	N, 89*50'E. on true line bet. Secs. 24 and 25	
	Va. 20*E.	
	Ascend	
2.00	Top of ridge Course S.85*E, N.85*W. Descend	+90
26.75	Creek 2 lks. wide Course S.60*E	-500
32.15	Creek 3 lks. wide Course S.40*E	
	Ascend	
40.00	Set dogwood post $4\frac{1}{2}$ ft. long 4 ins. sq. 24 ins. in the ground on hill side sloping SE for $\frac{1}{4}$ Sec. Cor. Marked $\frac{1}{4}$ S. on the N. face, from which	
	A Fir, 30 ins. diam. bears N.23*15'E., 54 lks. dist. Marked $\frac{1}{4}$ S. B T	
	A Fir, 5 ins. diam. bears S.42*E., 12 lks. dist. Marked $\frac{1}{4}$ S B T.	
44.75	Creek 1 lk. wide Course S.	
58.75	Enter Land Slide	
64.00	Leave Land Slide	
82.70	Intersected East Boundary of Tp. 4.20 chs. South of Cor.	