

Resurvey of W. Bdy. of T. 22 S. R. 6 W. W. M.

CHAINS

This cor. is on the S. slope of ridge, about 300 ft. below top. I could find no trace of the old  $\frac{1}{2}$  sec. cor.

49.00 Foot of descent; leave heavy timber; thence, across bottom land, and clearing owned by Cooper brothers, 100 ft. below  $\frac{1}{2}$  sec. cor.

55.00 Creek, 12 lks. wide, course W., leave bottom land, enter heavy timber, and ascend.

58.23 Creek, 6 lks. wide, course NW.

60.25 Same creek, 6 lks. wide, course N.20\*E.

73.45 Same creek, course N.20\*W.

79.25 Top of spur, slopes E. 250 ft. above foot of ascent.

80.00 Set a sandstone, 12x10x8 ins., 8 ins. in the ground, for cor. of secs. 19 and 30, mkd. with 4 notches on N. and 2 on S. edges; from which

A Fir, 36 ins. diam., bears N.80\*E., 91 lks. dist. mkd. T 22 S R 6 W S 19 B T.

A Maple, 12 ins. diam., bears S.20\*E., 21 lks. dist. mkd. T 22 S R 6 W S 30 B T.

This cor. is near the top of spur last noted.

From this cor., the old cor. of secs. 19, 30, 24 and 25, of which the only remaining indication is one bearing tree - bears S., about 150 lks. dist.

Land, mountainous; Soil, 2nd and 3rd rate.

Timber, Fir, Hemlock, Madrona, Maple, Chincapin, and Dogwood.

Dense undergrowth of Hazel, thimbleberry, salal berry, poison oak and ocean spray.

Mountainous land, heavily timbered or covered with dense undergrowth, 74.00 chs.

Nov.25: At the cor. of secs. 19, 30, 24 and 25; thence, I run South, on a true line, bet. secs. 25 and 30.

Mag. decl. 21\*30'E.

Descend.