

Resurvey of
5th Standard Parallel South, Range 6 W., W. M.

CHAINS

40.54 Creek, 5 lks. wide, course SW; ascend spur.

48.00 Top of spur, slopes SW., 75 ft. above last creek, descend.

64.26 Creek, 1 lk. wide, course S.50 ft. below top of spur.

72.07 Creek, 8 lks. wide, course N.80*W., 25 ft. below last creek; thence along creek bottom land.

73.55 Same creek, course S.85*W.

75.50 Same creek, course N.75*W.

77.10 Same creek, course S.80*W.,

77.80 Same creek, course N.60*W., begin ascent.

79.92 The standard cor. of secs. 5 and 6, 35 ft. above creek;
I reestablished this cor. Nov.24, 1897.

Land, mountainous.

Soil, 2nd and 3rd rate.

Timber, Fir, hemlock, cedar, maple, alder, dogwood and chincapin.

Dense undergrowth of thimble-berry, hazel, ocean spray, hemlock and salal-berry.

Mountainous land, heavily timbered or covered with dense undergrowth 79.92 chs.

I have thus completed this resurvey, and established the cors. thereon at proportionate distances to their respective original distances in accordance with the advise of the circular issued by the General Land Office on "Restoration of lost and obliterated corners," dated March 13, 1873.

The original standard cors. on the 5th Standard Parallel South, through R. 6 W., were established to refer to the secs. on the south; therefore establish the cors. on the resurveyed part of same with the bearings on the south, to preserve the uniformity of the cors., throughout the line.. Nov.30, 1897.