

Resurvey of 5th Standard Parallel S., through R. 6 W., W. M.

CHAINS

## GENERAL DESCRIPTION.

The resurveyed portion of this line described in the foregoing field notes is in a rough and mountainous country.

It is covered with a dense undergrowth of Hazel, vine-maple, salal-berry, salmon-berry, thimble berry, and willow.

The land is generally heavily timbered with fir, cedar, hemlock, maple, madrona, dogwood, alder and yew.

November 30, 1897.

Subdivisions of T. 22 S., R. 6 W., W. M. as surveyed by Carl S. Nicklin, Deputy Surveyor, under contract No. 664, dated May 23, 1896.

Retracement of line between secs. 34 & 35.

For the purpose of locating the cor. of secs. 26, 27, 34 and 35, I retrace the line bet. secs. 34 and 35, with the following result.

From the closing cor. of secs. 34 and 35, T. 22 S., R. 6 W., which is a post, 24 ins. above ground, 4 ins. sq., mkd. and witnessed as described by the Surveyor general,

I run

North, on a blank line, bet. secs. 34 and 35.

41.18 To a point, 6 lks. W. of the  $\frac{1}{4}$  sec. cor; which is a post, 3 ins. sq., 20 ins. above ground, mkd. and witnessed as described by the surveyor general.

82.22 To a point, 12 lks. W. of the cor. of secs. 26, 27, 34 and 35, which is a post, 4 ins. sq., 20 ins. above ground, mkd. and witnessed as described by the surveyor general.

Therefore this line bears N.0\*5'E.

Thence, I run

West, on a random line, bet. secs. 27 and 34.

40.00 Set a temp.  $\frac{1}{4}$  sec. cor.

79.95 To a point, 377 lks. S. of the cor. of secs. 27, 28, 33, and 34, post badly decayed some of the bearing trees down; I reestablished this cor., at same point as follows: