

Subdivisions of T. 22 S., R. 6 W., W. M.

CHAINS	
	North, on a blank line, bet. secs. 20 and 21.
40.00	After diligent search, I could find no trace of the $\frac{1}{4}$ sec. cor.
78.22	To a point, 100 lks. W. of the cor. of secs. 16, 17, 20 and 21, which is a post, 4 ins. sq., 15 ins. above ground, mkd. and witnessed as described by the surveyor general. Therefore, this line bears N.0*43'E.
	West, on a blank line, bet. secs. 17 and 20.
39.92	To a point, 22 lks. N. of the $\frac{1}{4}$ sec. cor, which is a post, 4 ins. sq., 18 ins. above ground, mkd. and witnessed as described by the surveyor general.
79.90	To a point, 47 lks. N. of the cor. of secs. 17, 18, 19 and 20; post decayed; bearing trees all standing and agree with the description furnished by the surveyor general; at same point, I Set a sandstone, 16x10x6 ins. , 11 ins. in the ground, for cor. of secs. 17, 18, 19 and 20, mkd. with 5 notches on E. and 3 notches on S. edges. Therefore this line bears S.89*40'W., Dec. 1, 1897.
	S.89*47'W., on a blank line bet. sec. 18 and 19.
38.75	To a point, 7 lks. N. of the $\frac{1}{4}$ sec. cor. post, badly decayed; bearing trees standing and agree with the description furnished by the surveyor general; at same point I Set a sandstone, 12x10x8 ins. , 8 ins. in the ground, for $\frac{1}{4}$ sec. cor., mkd. $\frac{1}{4}$ on N. face.
78.02	To a point, 12 lks. N. of the cor. of secs. 18, 19, 13 and 24, on W. Bdy. of T. 22 S., R. 6 W., which I reestablished Nov. 25, 1897. Therefore this line bears S.89*42'W.