

Subdivisions of T. 22 S., R. 7 W., W. M.

CHAINS	
61.80	Spur, slopes S.80*E., 100 ft. below top of ridge.
62.29	A Fir, 54 ins. diam., on line, I mark with 2 notches on E. and W. sides.
73.70	Ravine, course N.80*E., 350 ft. below last spur; continue descent.
75.35	Spur, slopes S., 25 ft. below ravine.
86.84	The cor. of secs. 25, 26, 35 and 36, 75 ft. below top of last spur.
	Land, mountainous.
	Soil, 3rd rate.
	Timber, Fir, Cedar, Hemlock, and Maple.
	Dense undergrowth of Vine maple, Hazel, Ocean-spray, Thimble-berry and Salmon-berry.
	Mountainous land, heavily timbered or covered with dense undergrowth, 86.84 chs. Nov. 26, 1897.
	The falling of the line bet. secs. 26 and 35, exceeding the prescribed limits for closing, I retrace the West Bdys. of secs. 26 and 35, to find the error.
	From the cor. of secs. 27 and 34, above described, I run South, on a blank line, bet. secs. 34 and 35.
40.74	The Qr. sec. cor., bet. secs. 34 and 35, which is a post, 4 ins. sq., 16 ins. above ground, mkd. and witnessed as described by the Surveyor General.
83.31	Intersect the 5th Standard Parallel, South, 6.75 chs. W. of the Standard cor. of secs. 2 and 3, T. 23 S., R. 7 W.; post destroyed; I reestablish this cor. from the bearing trees as follows: Set a Sandstone, 14x12x5 ins., 9 ins. in the ground for a Standard cor. of secs. 2 and 3, T. 23 S., R. 7 W., mkd. S C on S., with 2 grooves on E., and 4 grooves on W. faces; from which A Fir, 24 ins. diam., bears S.15*W., 10 lks. dist. mkd. T 23 S R 7 W S 3 B T. A Dogwood, 6 ins. diam., bears S.50*E., 30 lks. dist. mkd. T 23 S R 7 W S 2 B T .