

## Meanders of T. 22 S., R. 9 W.

CHAINS

The meander posts and witness trees along the river on the North side have all been destroyed or washed away. As I failed in every attempt to find one, and the citizens appear to know nothing about them since the high waters of 1861 and 1862.

Portions of the fractional Township, North of the river should be surveyed, but all of the old lines will necessarily have to be re-run.

West Bdy. of T. 22 S., R. 9 W.,  
As surveyed by W. H. Byars, Deputy Surveyor,  
Under Contract No. 274, dated Sept. 10, 1877.

Beginning at corner to secs. 18 and 19, T. 22 S., R. 9 W., and secs. 13 and 24, R. 10 W. I run South on old line.  
Va. 19°E.

- 40.00 Set a Fir post, 40 ins. long, 6 ins. diam., 12 ins. in ground, from which,  
A Maple, 10 ins. diam., bears N.10°E., 49 lks. dist.  
A Chinquapin, 6 ins. diam., bears N.52°W., 37 lks. dist.  
This line was compelled to be run in order to re-establish this corner, as a fire had destroyed the old corner.
- 43.00 A creek, 3 lks. wide, Course W.
- 52.00 A creek, 10 lks. wide, Course N.20°W.
- 55.00 A creek, 2 lks. wide, Course NE.
- 76.00 A creek, 2 lks. wide, Course NE.
- 80.00 Set a Fir post, 48 ins. long, 5 ins. diam., 20 ins. in ground, for corner to secs. 19, 24, 25 and 30, from which,  
A Yew, 10 ins. diam., bears N.80°E., 20 lks. dist.  
A Yew, 12 ins. diam., bears S.85°E., 25 lks. dist.  
A Fir, 48 ins. diam., bears S.40°W., 127 lks. dist.