

Subdivisions of T. 22 S., R. 9 W.

CHAINS

48.50 A creek, 1 lk. wide, Course SE.

75.50 A creek, 4 lks. wide, Course S.

79.86 To sec. corner.

Land, broken, brushy, third rate.

Timber, not good.

West, on Random line, between secs. 30 and 31.

Va. 19°E.

40.00 Set temporary  $\frac{1}{2}$  sec. corner.

80.44 Intersect line, 50 lks. South of post.

South, 89°39'E., on true line.

36.00 Top of spur, Course S.

36.50 Trail to Camp creek.

40.44 Marked a Fir tree, 24 ins. diam., for the  $\frac{1}{2}$  sec. corner.

77.00 A creek, 2 lks. wide, Course SE.

80.44 To sec. corner.

Land, mountainous, third rate.

Timber, young, second rate.

March 27, 1878.

Subdivisions of T. 22 S., R. 9 W.,  
As surveyed by Elmer O. Werrick, Deputy Surveyor,  
Under Contract No. 632, dated April 28, 1894.

Commenced at the corner to secs. 1, 2, 11 and 12, which

I re-established, as follows:

Set a Fir post, 4 $\frac{1}{2}$  feet long, 4 ins. square, 24 ins. in the ground, Marked T. 22, S. S 1 on the N. E. R. 9 W., S. 12 on the SE. S 11 on the SW. and S. 2 on the NW., faces with 5 notches on the S. and 1 notch on the E. edges, from which,

A Fir, 10 ins. diam., bears N.43°E., 182 lks. dist., marked T. 22 S., R. 7 W., S. 1 B. T.